



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 145
Colour	Grey
Year of manufacture	2007
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J









Internet history

Entry 1

Date	2021-06-06
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-28
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	14

MOT #19	2023-11-15 10:20
MOT test number	247261623849
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn On Edges (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn On Edges (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18	2022-11-23 10:37
MOT test number	187667156984
Result	✓ Passed

MOT #17	2021-11-03 18:40
MOT test number	171697458521
Result	✓ Passed

**MOT #16** 2020-10-29 11:48**MOT test number** 336093831776**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii))**Advice** Corrosion on the rear suspension components**MOT #15** 2019-05-28 14:33**MOT test number** 776953078275**Result** ✓ Passed**MOT #14** 2018-05-24 10:16**MOT test number** 651533473849**Result** ✓ Passed**MOT #13** 2018-05-24 10:15**MOT test number** 558747552617**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too far to the right (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**MOT #12** 2017-05-23 09:46**MOT test number** 599761670530**Result** ✓ Passed**MOT #11** 2017-05-23 09:07**MOT test number** 279179169863**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #10	2016-05-28 08:54
MOT test number	757519451488
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9	2016-05-28 08:54
MOT test number	156397157446
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #8	2015-05-29 08:33
MOT test number	776269145140
Result	✓ Passed

MOT #7	2014-05-28 11:55
MOT test number	446658744145
Result	✓ Passed

**MOT #6** 2014-05-13 11:09**MOT test number** 897383934130**Result** ✗ Failed

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #5 2013-05-02 11:50**MOT test number** 337552223125**Result** ✓ Passed

- Advice** Offside Rear Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2012-05-08 14:49**MOT test number** 989409922114**Result** ✓ Passed**MOT #3** 2011-09-30 11:57**MOT test number** 876183571208**Result** ✓ Passed

- Notice** Both rear tyres on 2mm
- Notice** Offside front tyre on 2mm
- Notice** Nail in offside rear tyre
- Notice** Both rear tyres cracking badly



MOT #2	2011-09-30 11:57
MOT test number	575543271272
Result	✗ Failed
Notice	Offside front tyre on 2mm
Notice	Nail in offside rear tyre
Pass with rectification	Offside Headlamp aim too high (1.8)
Notice	Both rear tyres cracking badly
Notice	Both rear tyres on 2mm
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #1	2010-09-28 12:25
MOT test number	282141370293
Result	✓ Passed
Notice	Rear tyres perished & starting to crack



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
28 November 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	K400KSW
Plate since	2019-03-29
Current registration	K400KSW
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-01
Last registration	2023-11-15
Complete history	See info



Registration #1	2007-09-01	16 mi
Registration #2	2010-09-28	42.286 mi
Registration #3	2011-09-30	57.899 mi
Registration #4	2012-05-08	63.796 mi
Registration #5	2013-05-02	72.487 mi
Registration #6	2014-05-13	79.991 mi
Registration #7	2014-05-28	80.443 mi
Registration #8	2015-05-29	88.104 mi
Registration #9	2016-05-28	95.506 mi
Registration #10	2016-05-28	95.506 mi
Registration #11	2016-05-28	95.506 mi
Registration #12	2016-05-28	95.506 mi
Registration #13	2016-05-28	95.506 mi
Registration #14	2016-05-28	95.506 mi
Registration #15	2016-05-28	95.506 mi
Registration #16	2016-05-28	95.506 mi
Registration #17	2016-05-28	95.506 mi
Registration #18	2016-05-28	95.506 mi
Registration #19	2016-05-28	95.506 mi
Registration #20	2016-05-28	95.506 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1479 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7L08751