





report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Red
Year of manufacture	2015
Top speed	125 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



W19SJE report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-17

Pictures 29

Listing price View report









source: yesauto.com

Entry 1

2021-09-14 Date

29 **Pictures**

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT I	nistory
-------	---------

MOT expiry date	2025-03-17
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #7	2024-03-14 14:30
MOT test number	684289134616
Result	✓ Passed
Next expiry date	2025-03-17

MOT #6		2023-03-07 14:04
MOT test	number	921021027664
Result		✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-03-05 13:47
MOT test number	599060227754
Result	✓ Passed
MOT #4	2021-03-18 12:59
MOT test number	290119556217
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3	2020-10-09 10:17
MOT test number	512700506114
Result	✓ Passed
MOT #2	2019-10-02 11:46
MOT test number	799294683605
Result	✓ Passed
Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))	

MOT #1		2018-10-12 10:46
MOT test	number	634743033937
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



W19SJE report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 8/11



W19SJE report date: 2024-03-28

Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-10-27
Last registration	2024-03-14
Complete history	See info



Registration #1	2015-10-27	6 mi
Registration #2	2018-10-12	33.548 mi
Registration #3	2019-10-02	43.363 mi
Registration #4	2020-10-09	44.135 mi
Registration #5	2021-03-18	45.354 mi
Registration #6	mm.m.m	11.777 46
	2000-20-20 2000-20-20	11.777 es
Registration #6	900-0-0 900-0-0 900-0-0	11.777 es 21.777 es 21.777 es
Registration #6 Registration #7	900-0-0 900-0-0 900-0-0	11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2AR1249887