



report date: 2024-03-28

General information

Make	SUZUKI
Model	CELERIO SZ3
Colour	Red
Year of manufacture	2015
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-18
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-27
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	21
Total items failed	0

MOT #7 2024-02-19 14:48

MOT test number 771793588454

Result ✓ Passed

Next expiry date 2025-02-27

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Items removed from driver's view prior to test

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2023-02-18 09:57

MOT test number 312093003760

Result ✓ Passed

MOT #5 2022-02-28 10:12

MOT test number 581955564509

Result ✓ Passed

**MOT #4**

2021-06-15 12:50

**MOT test number**

124873704868

**Result**

✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3**

2020-11-26 10:41

**MOT test number**

518391683040

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Nail in tyre
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material most corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2**

2019-05-15 10:09

**MOT test number**

884994135511

**Result**

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Non obligatory mirror damaged
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2018-06-20 12:36
MOT test number	604286280154
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Offside Non obligatory mirror damaged



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-30
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2015-06-30	21 mi
Registration #2	2018-06-20	14.738 mi
Registration #3	2019-05-15	19.123 mi
Registration #4	2020-11-26	25.767 mi
Registration #5	2021-06-15	28.227 mi
Registration #6	2022-06-20	35.277 mi
Registration #7	2023-06-20	42.327 mi
Registration #8	2024-02-19	49.377 mi
Registration #9	2024-02-19	49.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	61%
Children	74%
Pedestrian	68%
Safety systems	38%
Overall rating	60%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1540 mm
Length	3600 mm
Wheel base	2425 mm
Kerb weight	880 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K10BS1016592