



report date: 2025-02-13

General information

Make	KIA
Model	PRIDE SX
Colour	Blue
Year of manufacture	1999
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	63 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.324 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN



## Internet history

### Entry 4

Date	2021-09-06
Pictures	35
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date	2021-08-11
Pictures	35
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2021-07-25
Pictures	35
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-07-10
------	------------

Pictures

35

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT expiry date</b>	2021-10-09
<b>MOT pass rate</b>	65 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	8
<b>Total advice items</b>	38
<b>Total items failed</b>	15

MOT #23 2020-09-15 14:45

MOT test number 365225228496

Result ✔ Passed

Next expiry date 2021-10-09

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #22 2020-09-14 10:09

MOT test number 611043074725

Result ✘ Failed

**MAJOR** Offside Lower Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #21 2019-09-20 12:56

MOT test number 151925046164

Result ✔ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #20 2019-09-18 08:56

MOT test number 236507674989

Result ✘ Failed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19 2018-10-10 11:31

MOT test number 400377052862

Result ✔ Passed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #18 2017-09-12 11:21

MOT test number 647958184912

Result ✓ Passed

MOT #17 2016-09-26 13:47

MOT test number 344150056428

Result ✓ Passed

MOT #16 2015-10-01 14:56

MOT test number 172166295878

Result ✓ Passed

MOT #15 2015-10-01 09:45

MOT test number 802749590813

Result ✗ Failed

**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)

**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #14 2014-10-10 14:46

MOT test number 366993084417

Result ✓ Passed

MOT #13 2014-10-09 10:54

MOT test number 435822684242

Result ✗ Failed

**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)

**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

**Fail** Battery insecure (1.9.1)



<b>MOT #12</b>	2013-08-23 12:47
<b>MOT test number</b>	556235033284
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2012-09-03 13:38
<b>MOT test number</b>	705697742265
<b>Result</b>	✓ Passed
<b>Notice</b>	O/s/r tyre cracking

<b>MOT #10</b>	2012-08-31 10:36
<b>MOT test number</b>	115544642235
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear wheel bearing rough when rotated (2.6.1)
<b>Advice</b>	Offside Rear wheel bearing has slight play (2.6.2)
<b>Fail</b>	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>Fail</b>	Offside Rear wheel bearing rough when rotated (2.6.1)
<b>Notice</b>	O/s/r tyre cracking

<b>MOT #9</b>	2011-08-24 11:19
<b>MOT test number</b>	686516031284
<b>Result</b>	✓ Passed
<b>Notice</b>	O/s/r tyre cracking
<b>Notice</b>	O/s/f tyre cracking
<b>Notice</b>	N/s/r tyre cracking



**MOT #8** 2010-09-02 13:24

**MOT test number** 141225540264

**Result** ✓ Passed

- Notice** N/s/r tyre cracking
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7** 2010-09-02 11:19

**MOT test number** 693605840269

**Result** ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice** N/s/r tyre cracking
- Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #6** 2009-08-10 17:03

**MOT test number** 922762429294

**Result** ✓ Passed

**MOT #5** 2008-09-01 14:14

**MOT test number** 371305448447

**Result** ✓ Passed

- Notice** N/S & O/S/F Tyres Starting To Wear On Edges
- Notice** N/S & O/S/F T.C.A Bushes Starting To Wear
- Notice** Tyre Treads Just Starting To Crack Slightly





**MOT #4** 2008-09-01 14:14

**MOT test number** 714615948203

**Result** ✗ Failed

**Notice** Tyre Treads Just Starting To Crack Slightly

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Notice** N/S & O/S/F Tyres Starting To Wear On Edges

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Notice** N/S & O/S/F T.C.A Bushes Starting To Wear

**MOT #3** 2007-09-06 12:42

**MOT test number** 570329647294

**Result** ✓ Passed

**MOT #2** 2007-09-06 11:11

**MOT test number** 382969647419

**Result** ✗ Failed

**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

**MOT #1** 2006-09-06 09:23

**MOT test number** 493269246247

**Result** ✓ Passed




**Damage history**

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra KIA salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	V612EDK
Plate since	2019-09-29
Current registration	V612EDK
Plate since	2019-09-29

More info >



**Finance check**

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	27
<b>First mileage registration</b>	1999-09-07
<b>Last registration</b>	2020-09-15
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	1999-09-07	15 mi
<b>Registration #2</b>	2006-09-06	14,698 mi
<b>Registration #3</b>	2007-09-06	16,127 mi
<b>Registration #4</b>	2007-09-06	16,127 mi
<b>Registration #5</b>	2008-09-01	17,618 mi
<b>Registration #6</b>	2009-08-10	19,185 mi
<b>Registration #7</b>	2010-09-02	20,736 mi
<b>Registration #8</b>	2010-09-02	20,736 mi
<b>Registration #9</b>	2011-08-24	22,046 mi
<b>Registration #10</b>	2012-08-31	23,369 mi
<b>Registration #11</b>	2012-09-03	23,369 mi
<b>Registration #12</b>	2013-08-23	24,660 mi
<b>Registration #13</b>	2014-10-09	26,191 mi
<b>Registration #14</b>	2014-10-10	26,191 mi
<b>Registration #15</b>	2015-09-01	27,514 mi
<b>Registration #16</b>	2015-09-01	27,514 mi
<b>Registration #17</b>	2015-09-01	27,514 mi
<b>Registration #18</b>	2015-09-01	27,514 mi
<b>Registration #19</b>	2015-09-01	27,514 mi
<b>Registration #20</b>	2015-09-01	27,514 mi
<b>Registration #21</b>	2015-09-01	27,514 mi
<b>Registration #22</b>	2015-09-01	27,514 mi
<b>Registration #23</b>	2015-09-01	27,514 mi
<b>Registration #24</b>	2015-09-01	27,514 mi
<b>Registration #25</b>	2015-09-01	27,514 mi
<b>Registration #26</b>	2015-09-01	27,514 mi

[More info >](#)



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1605 mm
Height	1460 mm
Length	3565 mm

Additional information

Number of axles	2
Engine number	B3000045265