



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-08
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-12-15
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #10	2021-12-16 16:11
MOT test number	511589597851
Result	✓ Passed
Next expiry date	2022-12-15

MOT #9	2021-05-13 09:54
MOT test number	396731556281
Result	✓ Passed

MOT #8	2020-07-20 15:03
MOT test number	816067321772
Result	✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Front Windscreen wiper blade defective both sides (3.4 (b) (i))

MOT #7	2019-06-10 11:11
MOT test number	255240555805
Result	✓ Passed

**MOT #6** 2018-04-10 08:48**MOT test number** 352345006297**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2018-04-06 14:07**MOT test number** 447312795590**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #4** 2017-03-03 15:51**MOT test number** 304545470181**Result** ✓ Passed**Advice** Nearside Front door mirror casing slightly damaged

**MOT #3**

2016-03-18 15:46

MOT test number

504997503804

Result

✓ Passed

- Advice** Nearside Front door mirror damaged
- Advice** Oil leak from gearbox drain plug
- Advice** Nearside Front tyre has slight damage to outer wall
- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear tyres have slight cracks in tread
- Advice** Lower front bumper damaged
- Advice** Nearside Front tyre worn on edges and wearing low
- Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Damage to nsr of vehicle
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #2

2015-03-23 12:10

MOT test number

699212685095

Result

✓ Passed

- Notice** Items removed from driver's view prior to test
- Notice** Nearside front tyre slightly wearing on outer edge

MOT #1

2014-04-04 16:24

MOT test number

746124994066

Result

✓ Passed

- Notice** Nail in nearside rear tyre



Tax & MOT check

✕
Untaxed

Tax expired:
4 February 2022

✕
MOT

Expired:
15 December 2022

Tax status	Expired at 4 February 2022
Days left	814 days too late
MOT expiry date	15 December 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LS11SXU
Plate since	2019-09-29
Current registration	 LS11SXU
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-31
Last registration	2021-12-16
Complete history	See info



Registration #1	2011-03-31	16 mi
Registration #2	2014-04-04	16.433 mi
Registration #3	2015-03-23	20.585 mi
Registration #4	2016-03-18	24.494 mi
Registration #5	2017-03-03	28.593 mi
Registration #6	2018-04-06	37.179 mi
Registration #7	2019-05-20	39.377 mi
Registration #8	2019-05-20	39.377 mi
Registration #9	2019-05-20	39.377 mi
Registration #10	2019-05-20	39.377 mi
Registration #11	2019-05-20	39.377 mi
Registration #12	2019-05-20	39.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429