



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Blue
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-06-24
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	31
Total items failed	8

MOT #18	2023-10-17 11:57
MOT test number	910388028638
Result	✓ Passed
Next expiry date	2024-10-18
Advice	Front Sub-frame corroded but not seriously weakened rear (5.3.3 (b) (i))
Advice	All rear components corroded

MOT #17	2022-10-19 08:33
MOT test number	283457325094
Result	✓ Passed

MOT #16	2021-12-07 11:41
MOT test number	509226214872
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge Both 205/55/16 91v imperial (5.2.3 (e))

**MOT #15** 2021-12-06 09:44**MOT test number** 645541082081**Result** ✗ Failed**DANGEROUS** Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))**MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge Both 205/55/16 91v imperial (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #14** 2020-11-25 10:56**MOT test number** 345974583646**Result** ✓ Passed**MOT #13** 2019-05-30 09:56**MOT test number** 210679189139**Result** ✓ Passed**MOT #12** 2019-05-28 09:39**MOT test number** 470316487400**Result** ✗ Failed**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #11** 2018-05-30 09:22**MOT test number** 972030046803**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10** 2017-05-26 10:19**MOT test number** 307741896388**Result** ✓ Passed**MOT #9** 2016-05-27 08:11**MOT test number** 249582828534**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #8** 2015-05-26 11:47**MOT test number** 797006945119**Result** ✓ Passed**MOT #7** 2014-05-29 16:33**MOT test number** 546239044195**Result** ✓ Passed**MOT #6** 2014-05-29 11:44**MOT test number** 296049144166**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-05-28 11:44**MOT test number** 897188643158**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-05-30 11:37**MOT test number** 618281552101**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2012-05-30 11:37**MOT test number** 728211852169**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #2 2011-07-01 14:59

MOT test number 369402281104

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Oil leak

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-06-28 11:16

MOT test number 835189971160

Result ✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Headlamp aim too low (1.8)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Offside Headlamp aim too low (1.8)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Oil leak



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-30
Last registration	2023-10-17
Complete history	See info



Registration #1	2008-06-30	27 mi
Registration #2	2011-06-28	30.483 mi
Registration #3	2011-07-01	30.556 mi
Registration #4	2012-05-30	38.945 mi
Registration #5	2013-05-28	44.334 mi
Registration #6	2014-05-29	50.672 mi
Registration #7	2014-05-29	50.672 mi
Registration #8	2015-05-26	55.306 mi
Registration #9	2016-05-27	60.632 mi
Registration #10	2017-05-26	65.900 mi
Registration #11	2018-05-26	71.168 mi
Registration #12	2019-05-26	76.436 mi
Registration #13	2020-05-26	81.704 mi
Registration #14	2021-05-26	86.972 mi
Registration #15	2022-05-26	92.240 mi
Registration #16	2023-05-26	97.508 mi
Registration #17	2023-10-17	102.776 mi
Registration #18		
Registration #19		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5364188