




report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 SE NAV
Colour	Silver
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	8

MOT #8	2024-02-21 11:05
MOT test number	148308775649
Result	✓ Passed
Next expiry date	2025-03-07

MOT #7	2023-02-22 12:10
MOT test number	548008636237
Result	✓ Passed

MOT #6	2022-02-15 15:30
MOT test number	338495610942
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5** 2022-02-14 16:54**MOT test number** 166541250581**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Brake performance not tested (1.2.1 (g))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #4** 2021-03-08 13:43**MOT test number** 816669432984**Result** ✓ Passed**MOT #3** 2021-03-08 13:43**MOT test number** 487122480181**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2020-09-08 08:37**MOT test number** 235910896793**Result** ✓ Passed



MOT #1	2019-08-29 14:57
MOT test number	135673365584
Result	✓ Passed
<div>AdviceAll 4 tyres worn on edges</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-23
Last registration	2024-02-21
Complete history	See info



Registration #1	2016-09-23	11 mi
Registration #2	2019-08-29	57.414 mi
Registration #3	2020-09-08	70.606 mi
Registration #4	2020-09-08	70.606 mi
Registration #5	2021-03-08	71.604 mi
Registration #6	2021-03-08	71.604 mi
Registration #7	2021-03-08	71.604 mi
Registration #8	2021-03-08	71.604 mi
Registration #9	2021-03-08	71.604 mi
Registration #10	2021-03-08	71.604 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1750 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1746148