



RENAULT

**YF590WP**

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE I-MUSIC VVT
Colour	Grey
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg





Internet history

Entry 1

Date	2021-07-16
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #10</b>	2021-01-22 10:43
<b>MOT test number</b>	550415352202
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-02-04
<b>Minor</b>	Central Stop lamp(s) emits other than a steady red light (4.3.3 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #9</b>	2020-01-24 09:29
<b>MOT test number</b>	303446067517
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #8</b>	2019-01-09 14:03
<b>MOT test number</b>	914795428492
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2018-01-18 09:56
<b>MOT test number</b>	622125634117
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2017-01-12 13:53**MOT test number** 156791800199**Result** ✓ Passed**Advice** Under-trays fitted obscuring some components on the underside of the car**MOT #5** 2016-02-05 12:21**MOT test number** 207426488788**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2015-01-12 09:37**MOT test number** 825622815085**Result** ✓ Passed**MOT #3** 2014-01-21 14:49**MOT test number** 429901324095**Result** ✓ Passed**MOT #2** 2014-01-21 14:49**MOT test number** 247711324010**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #1** 2013-01-22 12:17**MOT test number** 575362123008**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>YF59OWP</b>
Plate since	2019-03-29
Current registration	<b>YF59OWP</b>
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-01-28
Last registration	2021-01-22
Complete history	<a href="#">See info</a>



Registration #1	2010-01-28	25 mi
Registration #2	2013-01-22	14.766 mi
Registration #3	2014-01-21	19.678 mi
Registration #4	2015-01-12	22.202 mi
Registration #5	2016-02-05	23.766 mi
Registration #6	2017-01-12	27.754 mi
Registration #7	2018-01-22	28.277 mi
Registration #8	2019-01-22	28.277 mi
Registration #9	2020-01-22	28.277 mi
Registration #10	2021-01-22	28.277 mi
Registration #11	2022-01-22	28.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1734 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D056678