





report date: 2024-03-28

### General information

Make	MAZDA
Model	3 TS
Colour	Red
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



## Internet history

### Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-09
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #16	2024-02-08 13:41
MOT test number	514938042987
Result	✓ Passed
Next expiry date	2025-02-09

MOT #15		2024-02-08 13:41
MOT test number		451684197575
Result		<b>×</b> Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #14		2023-02-09 13:15
MOT test	number	211155111893
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/13



Result

NU60BJK report date: 2024-03-28

✓ Passed

MOT #13 2022-02-09 10:01

**MOT test number** 521702812464

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #12** 2022-02-05 10:46

**MOT test number** 182706282594

Result X Failed

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2021-02-10 11:21

MOT test number 644641394928

Result \( \sqrt{Passed} \)

**MOT #10** 2019-12-04 13:32

**MOT test number** 195623679394

**Result** 
✓ Passed

**Advice** Undertrays Fitted

**Advice** Engine Covers Fitted

CarCheck.co.uk page 4/13



**MOT #9** 2019-08-27 15:21

**MOT test number** 810048316883

MOT #8 2019-08-27 13:18

**MOT test number** 393896173746

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Valve stem seriously damaged (5.2.3 (j))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Valve stem seriously damaged (5.2.3 (j))

MOT #7 2018-08-24 09:37

**MOT test number** 604727522995

**Result** ✓ Passed

MOT #6 2017-08-30 15:27

**MOT test number** 801099418844

**Result** ✓ Passed

**MOT #5** 2017-08-30 09:37

**MOT test number** 666277514198

Result × Failed

**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)

**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside front brake binding (3.7.B.1)

CarCheck.co.uk page 5/13



Advice

NU60BJK report date: 2024-03-28

MOT #4 2016-08-26 09:22 **MOT test number** 956036302174 ✓ Passed Result MOT #3 2015-08-24 10:21 **MOT test number** 149373522741 Result Passed Advice Nail in nsr tyre tread Advice All 4 tyres getting low recommend attention

MOT #2	2014-08-26 12:16
MOT test number	608718834232
Result	✓ Passed
MOT #1	2013-08-22 11:46
MOT test number	647714933219
Result	✓ Passed

Slight binding of nsf brake possibly due to just being washed

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	9 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e union mestery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
********	
************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



## Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2024-02-08
Complete history	See info



Registration #1	2010-09-01	29 mi
Registration #2	2013-08-22	19.923 mi
Registration #3	2014-08-26	24.672 mi
Registration #4	2015-08-24	27.963 mi
Registration #5	2016-08-26	30.132 mi
Registration #6	2017-08-30	33.234 mi
Registration #7	2017-08-30	33.234 mi
Registration #8	2018-08-24	36.366 mi
Registration #9	2019-08-27	40.989 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		11.777 es
Registration #17		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



## Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4580 mm
Wheel base	2640 mm
Kerb weight	1235 kg
Max. allowed weight	1745 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	Z6 862414

CarCheck.co.uk page 13/13