



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 R-DESIGN
Colour	Red
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-01-22
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #9	2024-03-04 14:42
MOT test number	491989099248
Result	✓ Passed
Next expiry date	2025-03-06

MOT #8	2023-03-01 11:24
MOT test number	374308991864
Result	✓ Passed

MOT #7	2022-03-07 10:08
MOT test number	278811173671
Result	✓ Passed

MOT #6	2021-01-14 12:23
MOT test number	261012449108
Result	✓ Passed

**MOT #5** 2021-01-14 10:09**MOT test number** 975951688022**Result** ✗ Failed

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #4 2020-01-14 13:51**MOT test number** 221153360669**Result** ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-01-10 13:15**MOT test number** 786266313794**Result** ✓ Passed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #2 2018-01-15 11:41**MOT test number** 296169877520**Result** ✓ Passed



MOT #1	2017-01-27 10:45
MOT test number	176774569363
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KW63XWR
Plate since	2019-09-29
Current registration	KW63XWR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-01-30
Last registration	2024-03-04
Complete history	See info



Registration #1	2014-01-30	20 mi
Registration #2	2017-01-27	20.290 mi
Registration #3	2018-01-15	29.003 mi
Registration #4	2019-01-10	38.554 mi
Registration #5	2020-01-14	45.468 mi
Registration #6	2021-01-14	50.176 mi
Registration #7	2022-01-14	55.277 mi
Registration #8	2023-01-14	60.378 mi
Registration #9	2024-01-14	65.479 mi
Registration #10	2025-01-14	70.580 mi
Registration #11	2026-01-14	75.681 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1445 mm
Length	4369 mm
Wheel base	2646 mm
Kerb weight	1501 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1428876