





report date: 2024-03-28

General information

Make	FIAT
Model	500 C TWINAIR PLUS
Colour	Blue
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	А



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-21

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-10-18
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	20
Total items failed	12

MOT #12	2021-10-19 17:20
MOT test number	143025104804
Result	✓ Passed
Next expiry date	2022-10-18
Advice Rear Brake drum worn, but not excessively (1.1.14 (a) (i))	

MOT #11	2021-10-19 13:41
MOT test number	569896053087
Result	X Failed
Fail Nearside Front Headlamp aim too high (4.1.2 (a))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Rear Brake drum worn, but not excessively (1.1.14 (a) (i))	

MOT #10		2021-01-09 09:59
MOT test	number	691001718539
Result		✓ Passed
Advice	Offside Rear Bump stop defective	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/13



MOT #9 2020-02-01 17:57

MOT test number 164544535498

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Bump stop defective.

MOT #8 2020-01-21 15:22

MOT test number 848569265669

Result X Failed

Fail Offside Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Fail Nearside Front Bumper insecure (6.1.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Bump stop defective.

Fail Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Fog lamp fallen inside bumper.

MOT #7 2019-01-21 10:20

MOT test number 193572847509

Result

Passed

MOT #6 2018-04-06 14:50

MOT test number 545849232176

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement back bush (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/13



MOT #5 2018-03-29 16:23

MOT test number 674202708525

Result X Failed

Fail Nearside Front Brake hose has insufficient room to move, resulting in fouling on any part insecure (3.6.B.4a)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement back bush (2.4.G.2)

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Nearside Front Brake hose excessively damaged (3.6.B.4d)

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement back bush (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Coolant leak from bottle

Fail

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #4 2017-04-04 08:57

MOT test number 481568261771

Result Passed

MOT #3 2017-04-01 11:47

MOT test number 361591812804

Result X Failed

Fail Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Fail Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

MOT #2 2016-04-08 16:08

MOT test number 124993159254

Result ✓ Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

CarCheck.co.uk page 5/13



MOT #1 2015-04-10 13:31

MOT test number 738490205165 Result ✓ Passed **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Engine covers fitted obscuring some components in the engine bay Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/13



Tax & MOT check



Tax expired: 1 November 2022

X MOT

Expired: 18 October 2022

Tax status	Expired at 1 November 2022
Days left	544 days too late
MOT expiry date	18 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-24
Last registration	2021-10-19
Complete history	See info



Registration #1	2012-03-24	17 mi
Registration #2	2015-04-10	65.581 mi
Registration #3	2016-04-08	76.056 mi
Registration #4	2017-04-01	87.528 mi
Registration #5	2017-04-04	87.574 mi
Registration #6	2018-03-29	96.184 mi
Registration #7	2018-04-06	96.184 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1.

Number of axles 2

Engine number 0054800