





report date: 2024-03-29

## General information

Make	FORD
Model	FIESTA EDGE
Colour	Red
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date 2021-01-21

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-03-28
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	0

MOT #13		2024-03-29 18:29
MOT test	number	924422663077
Result		✓ Passed
Next expi	ry date	2025-03-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-03-01 09:29
MOT test number	819105290092
Result	<b>√</b> Passed
MOT #11	2022-02-03 14:00
MOT test number	855422516767
Result	<b>✓</b> Passed

MOT #10		2022-02-01 08:01
MOT test	number	566885053459
Result		<b>X</b> Failed
MAJOR	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))	

page 3/12 CarCheck.co.uk



Result

NI60NBB

report date: 2024-03-29

**MOT** #9 2021-03-01 17:27 **MOT** test number 656045969172

Result ✓ Passed

**MOT** #8 2021-02-26 15:56

**MOT** test number 335132730636

× Failed

Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) **MAJOR** 

**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) **MAJOR** 

**MAJOR** Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

**MOT #7** 2020-02-08 13:52

**MOT** test number 496333105987

Result ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**MOT #6** 2018-09-19 13:50

**MOT** test number 418698487986

Result ✓ Passed

**MOT #5** 2017-08-30 09:49

**MOT** test number 994192450298

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #4	2016-09-14 13:48
MOT test number	791970046142
Result	<b>✓</b> Passed
MOT #3	2015-09-14 15:36
MOT test number	778440672609
Result	✓ Passed
MOT #2	2014-09-10 15:49
MOT test number	115433054224
Result	<b>✓</b> Passed
MOT #1	2013-09-11 10:28
MOT test number	878954553217
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	28 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
**************************************		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-21
Last registration	2024-03-29
Complete history	See info



Registration #1	2010-09-21	15 mi
Registration #2	2013-09-11	8.155 mi
Registration #3	2014-09-10	12.645 mi
Registration #4	2015-09-14	14.317 mi
Registration #5	2016-09-14	18.398 mi
Registration #6	2017-08-30	20.414 mi
Registration #7	2018-09-19	22.213 mi
Registration #8	2020-02-08	32.985 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		N.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

# Additional information

Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/:

Number of axles 2

Engine number AU64848