



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | FORD |
| Model | S-MAX ZETEC TDCI |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 143 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-28 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-25 |
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 26 |
| Total items failed | 6 |

| | |
|------------------|--|
| MOT #17 | 2023-07-26 12:41 |
| MOT test number | 371027323602 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-25 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #16 | 2023-07-25 08:20 |
| MOT test number | 740324298128 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) |
| Advice | Nearside Rear Exhaust heat shield insecure |
| Fail | Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a)) |

| | |
|-----------------|------------------|
| MOT #15 | 2022-07-08 15:14 |
| MOT test number | 377542594053 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #14 | 2021-07-23 07:42 |
| MOT test number | 933575463928 |
| Result | ✓ Passed |

**MOT #13** 2021-02-22 13:41**MOT test number** 862944420236**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2021-02-22 11:52**MOT test number** 689253515729**Result** ✗ Failed**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2020-01-11 17:31**MOT test number** 641415195949**Result** ✓ Passed**MOT #10** 2019-02-05 09:40**MOT test number** 640244625470**Result** ✓ Passed**MOT #9** 2018-01-24 12:09**MOT test number** 288339387030**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

**MOT #8** 2017-01-24 09:51**MOT test number** 636779856609**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear exhaust heat shield insecure**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2016-01-14 09:32**MOT test number** 385261268900**Result** ✓ Passed**MOT #6** 2015-01-13 10:23**MOT test number** 545183615022**Result** ✓ Passed**MOT #5** 2014-01-10 11:55**MOT test number** 146400214004**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2014-01-10 11:29**MOT test number** 208320114029**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2013-01-14 11:07**MOT test number** 136714813084**Result** ✓ Passed**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in nearside rear tyre**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-01-16 13:54**MOT test number** 337276912064**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-01-16 13:54**MOT test number** 195176512061**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 25 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|--------------|--------|
| XXXXXX | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX | XXXXXX |
| XXXXXX | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX | XXXXXX |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | XXXXX |
| Plate since | 2019-09-29 |
| Current registration | XXXXX |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2009-01-26 |
| Last registration | 2023-07-26 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-01-26 | 27 mi |
| Registration #2 | 2012-01-16 | 41.144 mi |
| Registration #3 | 2013-01-14 | 49.801 mi |
| Registration #4 | 2014-01-10 | 57.355 mi |
| Registration #5 | 2014-01-10 | 57.355 mi |
| Registration #6 | 2015-01-13 | 68.040 mi |
| Registration #7 | 2016-01-14 | 76.032 mi |
| Registration #8 | 2017-01-24 | 84.714 mi |
| Registration #9 | 2018-01-24 | 92.453 mi |
| Registration #10 | 2019-01-26 | 101.277 mi |
| Registration #11 | 2019-01-26 | 101.277 mi |
| Registration #12 | 2019-01-26 | 101.277 mi |
| Registration #13 | 2019-01-26 | 101.277 mi |
| Registration #14 | 2019-01-26 | 101.277 mi |
| Registration #15 | 2019-01-26 | 101.277 mi |
| Registration #16 | 2019-01-26 | 101.277 mi |
| Registration #17 | 2019-01-26 | 101.277 mi |
| Registration #18 | 2019-01-26 | 101.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2154 mm |
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1897 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 8A81221 |