



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2012
Top speed	120 mph
0 - 100 km/h	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-04
Pictures	17
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-26
Pictures	17
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	11

MOT #14	2023-08-02 15:01
MOT test number	482903514158
Result	✓ Passed
Next expiry date	2024-08-03
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13	2023-08-02 12:10
MOT test number	342744801205
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm 225/50/17 (5.2.3 (e))
Advice	Undertray oily
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge STRONG ADVISE (5.2.3 (e))

MOT #12	2022-08-04 16:56
MOT test number	461346299275
Result	✓ Passed

**MOT #11** 2022-07-30 14:51**MOT test number** 550377642083**Result** ✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #10 2021-06-28 14:48**MOT test number** 943817921257**Result** ✓ Passed**MOT #9** 2020-11-11 15:58**MOT test number** 516170700733**Result** ✓ Passed**MOT #8** 2020-11-11 12:37**MOT test number** 999970873175**Result** ✗ Failed

Fail Offside Front Tyre has ply or cords exposed 225/50/17 (5.2.3 (d) (ii))

MOT #7 2019-11-07 13:00**MOT test number** 105607795718**Result** ✓ Passed

Advice Front discs worn ,advise renewing when pads required

Advice Front pads worn (limited vision on exact condition,advise wheels off inspection asap)

**MOT #6** 2018-11-03 09:11**MOT test number** 539787084775**Result** ✓ Passed**MOT #5** 2018-11-02 10:50**MOT test number** 112816572753**Result** ✗ Failed

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Suspension component pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2017-09-25 10:30**MOT test number** 731900666277**Result** ✓ Passed

Advice Rear tyres worn on inner edges

Advice Offside Front tyre has splits in outer side wall

Advice Front tyres worn on edges

**MOT #3** 2016-09-29 12:13**MOT test number** 905484544795**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Engine cover/under trays fitted
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Centre Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear tyres have slight edge wear

MOT #2 2015-09-29 12:02**MOT test number** 201296275679**Result** ✓ Passed**MOT #1** 2015-02-03 12:08**MOT test number** 869934835012**Result** ✓ Passed

- Notice** Off side and near side rear trailing arm front bushes starting to split
- Notice** Both rear tyres worn to limit



Tax & MOT check

X

Untaxed

Tax expired:
25 April 2024

✓

MOT

Expires:
3 August 2024

Tax status	Expired at 25 April 2024
Days left	5 days too late
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-03
Last registration	2023-08-02
Complete history	See info



Registration #1	2012-01-03	27 mi
Registration #2	2015-02-03	44.184 mi
Registration #3	2015-09-29	50.969 mi
Registration #4	2016-09-29	55.505 mi
Registration #5	2017-09-25	63.988 mi
Registration #6	2018-11-02	76.479 mi
Registration #7	2018-11-03	76.479 mi
Registration #8	2019-11-07	88.078 mi
Registration #9	2020-11-11	95.993 mi
Registration #10	2021-01-01	95.993 mi
Registration #11	2021-01-01	95.993 mi
Registration #12	2021-01-01	95.993 mi
Registration #13	2021-01-01	95.993 mi
Registration #14	2021-01-01	95.993 mi
Registration #15	2021-01-01	95.993 mi
Registration #16	2021-01-01	95.993 mi
Registration #17	2021-01-01	95.993 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	BM24168