



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R AWD
Colour	Beige
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-30
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	25
Total items failed	6

MOT #14	2024-01-24 08:29
---------	------------------

MOT test number	872273813294
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-23
------------------	------------

Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Fuel Pipe/s corroded
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Inner sill corroded thin

**MOT #13**

2024-01-17 09:07

MOT test number

637998153296

Result

✗ Failed

Advice Fuel Pipe/s corroded**Fail** Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner sill (6.1.1 (c) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Inner sill corroded thin**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12**

2023-01-18 14:08

MOT test number

287928063722

Result

✓ Passed

Advice Fuel Pipe/s corroded Fuel filler pipe**Advice** Offside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))**MOT #11**

2022-01-18 13:49

MOT test number

872955382498

Result

✓ Passed

MOT #10

2021-05-14 12:37

MOT test number

321938887106

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9** 2021-05-14 08:41**MOT test number** 732073944683**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**MOT #8** 2020-05-22 08:30**MOT test number** 500064596148**Result** ✓ Passed**MOT #7** 2019-06-14 09:51**MOT test number** 817292651221**Result** ✓ Passed**MOT #6** 2018-07-02 11:04**MOT test number** 618468858893**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #5** 2017-06-26 10:19**MOT test number** 184261299015**Result** ✓ Passed

**MOT #4** 2016-07-16 10:10**MOT test number** 532059606772**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to the legal limit edge (4.1.E.1)**Advice** Offside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**MOT #3** 2015-07-14 11:45**MOT test number** 106695395181**Result** ✓ Passed**MOT #2** 2014-07-25 14:54**MOT test number** 675056104288**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-08-16 11:42**MOT test number** 418228123249**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
23 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-01
Last registration	2024-01-24
Complete history	See info



Registration #1	2010-09-01	7 mi
Registration #2	2013-08-16	17.262 mi
Registration #3	2014-07-25	27.631 mi
Registration #4	2015-07-14	33.444 mi
Registration #5	2016-07-16	45.300 mi
Registration #6	2017-06-26	54.447 mi
Registration #7	2018-07-02	66.178 mi
Registration #8	2019-06-14	78.166 mi
Registration #9	2020-06-20	90.154 mi
Registration #10	2021-06-20	102.142 mi
Registration #11	2022-06-20	114.130 mi
Registration #12	2023-06-20	126.118 mi
Registration #13	2024-01-24	138.106 mi
Registration #14	2024-01-24	150.094 mi
Registration #15	2024-01-24	162.082 mi
Registration #16	2024-01-24	174.070 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4335 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0321838