



RENAULT

SJ60XDZ

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE GENERATION VVT
Colour	Black
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





MOT history

MOT expiry date	2020-10-10
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	37
Total items failed	8

MOT #172021-03-24 16:15

MOT test number110155907506

Result	✗ Failed
MAJOR	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear greased/corroded (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material greased/corroded (1.1.11 (c))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Play in steering rack inner joint(s)
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear greased/corroded (1.1.11 (c))
MAJOR	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material greased/corroded (1.1.11 (c))
Advice	Handbrake has little reserve travel
Advice	Brake disc worn, pitted or scored, but not seriously weakened front discs (1.1.14 (a) (ii))
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Horn not working (7.7 (a) (ii))

**MOT #16** 2019-10-08 11:19**MOT test number** 553882157561**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-10-11 09:43**MOT test number** 197552966457**Result** ✓ Passed**MOT #14** 2018-05-22 11:14**MOT test number** 850044944181**Result** ✓ Passed**MOT #13** 2018-05-21 12:20**MOT test number** 199980443230**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #12** 2018-01-11 15:56**MOT test number** 427525760969**Result** ✓ Passed

**MOT #11** 2018-01-11 09:26**MOT test number** 302188668790**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Rear rear brake binding (3.7.B.1)**MOT #10** 2017-08-12 08:18**MOT test number** 538469536140**Result** ✓ Passed**MOT #9** 2017-08-11 09:32**MOT test number** 930080935861**Result** ✗ Failed**Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-03-24 09:45**MOT test number** 400155205053**Result** ✓ Passed

**MOT #7** 2017-03-23 12:30**MOT test number** 385714201788**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim too high (1.8)**MOT #6** 2016-05-02 12:09**MOT test number** 718520036440**Result** ✓ Passed**Advice** Rear both rear brakes sticking slightly**Advice** Tyre worn close to the legal limit all 4 tyres on 2-3mm low but not illegal (4.1.E.1)**MOT #5** 2015-05-07 11:00**MOT test number** 225277125416**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Suspect wrong tyre size fitted to car**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-05-16 16:18**MOT test number** 268206734112**Result** ✓ Passed

**MOT #3** 2014-05-14 10:07**MOT test number** 987274734157**Result** ✗ Failed**Pass with rectification** Offside Front Front drive shaft coupling is insecure (2.5.C.1c)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2013-08-24 11:14**MOT test number** 637146333239**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-08-24 09:59**MOT test number** 646136233231**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✕
Untaxed

Tax expired:
16 February 2021

✕
MOT

Expired:
10 October 2020

Tax status	Expired at 16 February 2021
Days left	1168 days too late
MOT expiry date	10 October 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2021-03-24
Complete history	See info



Registration #1	2010-09-01	18 mi
Registration #2	2013-08-24	21.743 mi
Registration #3	2013-08-24	21.743 mi
Registration #4	2014-05-14	26.695 mi
Registration #5	2014-05-16	26.695 mi
Registration #6	2015-05-07	32.878 mi
Registration #7	2016-05-02	39.045 mi
Registration #8	2017-03-23	44.120 mi
Registration #9	2017-03-24	44.121 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2641 mm
Kerb weight	1200 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	R013871