



PEUGEOT



YAI2HWE

report date: 2024-03-28

General information

Make	PEUGEOT
Model	508 HDI SW ACTIVE
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	58.9 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-09-08
Pictures	28
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	35
Total items failed	6

MOT #12 2023-10-24 09:28

MOT test number 673053092162

Result ✓ Passed

Next expiry date 2024-11-02

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #11 2022-10-27 11:23

MOT test number 360344893174

Result ✓ Passed

MOT #10 2021-11-03 11:45

MOT test number 815446003861

Result ✓ Passed

- Advice** Coil springs corroded-rear shocker bushes perished slightly-front tyres on limit-

**MOT #9** 2021-08-24 15:07**MOT test number** 150016271483**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #8** 2020-08-24 14:04**MOT test number** 229891888623**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-08-27 09:12**MOT test number** 694746343372**Result** ✓ Passed**MOT #6** 2018-08-29 12:09**MOT test number** 780210406778**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))



MOT #5	2018-08-28 10:57
MOT test number	625099581896
Result	✗ Failed
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Fail	Offside Front Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))

MOT #4	2017-08-26 09:06
MOT test number	183260232364
Result	✓ Passed
Advice	Offside Front tyre starting to wear on edges
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened surface corrosion (3.5.1i)
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint drop link (2.4.G.2)
Advice	Nearside Front tyre worn on the edges
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint drop link (2.4.G.2)

**MOT #3** 2017-08-26 09:06**MOT test number** 700469164913**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened surface corrosion (3.5.1i)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint drop link (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front tyre worn on the edges**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint drop link (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front tyre starting to wear on edges**MOT #2** 2016-07-01 07:59**MOT test number** 635214888038**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #1** 2015-06-04 09:50**MOT test number** 159715055121**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-30
Last registration	2023-10-24
Complete history	See info



Registration #1	2012-06-30	8 mi
Registration #2	2015-06-04	44.267 mi
Registration #3	2016-07-01	59.293 mi
Registration #4	2017-08-26	77.353 mi
Registration #5	2017-08-26	77.353 mi
Registration #6	2018-08-28	94.180 mi
Registration #7	2018-08-29	94.180 mi
Registration #8	2019-05-29	111.277 mi
Registration #9	2019-05-29	111.277 mi
Registration #10	2019-05-29	111.277 mi
Registration #11	2019-05-29	111.277 mi
Registration #12	2019-05-29	111.277 mi
Registration #13	2019-05-29	111.277 mi
Registration #14	2023-10-24	111.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1476 mm
Length	4813 mm
Wheel base	2817 mm
Kerb weight	1681 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	DYZA4009658