





report date: 2024-03-28

General information

Make	MERCEDES
Model	C C200 KOMPRESSOR SPORT
Colour	Silver
Year of manufacture	2008
Top speed	143 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 5.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-02

Pictures 47

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-12
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #15		2023-06-12 11:55
MOT test	number	632708924722
Result		✓ Passed
Next exp	iry date	2024-06-12
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b)	(i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #14 2023-06-07 13:35

MOT test number 407174852868

Result X Failed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MAJOR Rear Registration plate does not conform to the specified requirements Incorrect Spacing. (0.1 (d))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer Sidewall. (5.2.3 (d) (i))

MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #13 2022-06-13 13:23

MOT test number 271596535515

Result ✓ Passed

MOT #12 2021-09-13 11:40

MOT test number 628180608962

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

MOT #11 2021-01-18 12:48

MOT test number 667517024637

Result
✓ Passed

CarCheck.co.uk page 4/13



MOT #4

Result

MOT test number

KL08HXV

report date: 2024-03-28

2014-01-06 12:38

976406304012

✓ Passed

MOT #10	2020-02-01 15:01
MOT test number	185705313551
Result	✓ Passed
MOT #9	2019-02-12 17:10
MOT test number	425511079028
Result	✓ Passed
MOT #8	2018-01-08 11:07
MOT test number	980692714561
Result	✓ Passed
MOT #7	2017-01-09 13:12
MOT test number	809295637346
Result	✓ Passed
Advice Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice Nearside Front wheel bearing has slight play (2.5.A.3c)	
MOT #6	2016-01-04 14:10
MOT test number	264147024255
Result	✓ Passed
MOT #5	2015-01-06 13:30
MOT test number	137436205461
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3	2012-12-21 16:27
MOT test number	766106152301
Result	✓ Passed
MOT #2	2012-01-05 17:03
MOT test number	288295002075
Result	✓ Passed
MOT #1	2011-01-11 16:46
MOT test number	165421211090
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid utitil 1 January
Days left	247
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-04
Last registration	2023-06-12
Complete history	See info



Registration #1	2008-03-04	22 mi
Registration #2	2011-01-11	21.853 mi
Registration #3	2012-01-05	24.744 mi
Registration #4	2012-12-21	28.356 mi
Registration #5	2014-01-06	31.062 mi
Registration #6	2015-01-06	36.029 mi
Registration #7	2016-01-04	39.553 mi
Registration #8	2017-01-09	43.659 mi
Registration #9	2018-01-08	47.040 mi
Registration #10		10.777 au
3.0 3.0 a.		
Registration #11		11.777 mi
-		11.777 es
Registration #11		11.777 es 11.777 es 11.777 es
Registration #11 Registration #12		11.777 es
Registration #11 Registration #12 Registration #13		77.777-66 77.777-66 77.777-66 77.777-66
Registration #11 Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	2020 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	27195031130662

CarCheck.co.uk page 13/13