



ET570BC

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg





Internet history

Entry 1

Date	2021-09-28
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #13** 2021-10-01 08:52**MOT test number** 594415570866**Result** ✓ Passed**Next expiry date** 2022-09-30**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2021-09-29 13:39**MOT test number** 222242672724**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Offside Headlamp lens slightly defective faded (4.1.1 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Position lamp showing red light to the front multi coloured (4.2.3 (a) (ii))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/45/16 (5.2.3 (e))**Minor** Nearside Headlamp lens slightly defective faded (4.1.1 (b) (i))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Front Position lamp showing red light to the front multi coloured (4.2.3 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

**MOT #11** 2021-09-28 10:42**MOT test number** 977158843792**Result** ✗ Failed**Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Rear Exhaust has a major leak of exhaust gases silencer box missing (6.1.2 (a))**MOT #10** 2020-09-30 13:30**MOT test number** 787539016569**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9** 2019-09-14 10:02**MOT test number** 844707148203**Result** ✓ Passed**MOT #8** 2018-09-19 14:54**MOT test number** 707392477378**Result** ✓ Passed**MOT #7** 2017-05-12 12:37**MOT test number** 398295432199**Result** ✓ Passed**MOT #6** 2015-10-01 08:54**MOT test number** 532090044760**Result** ✓ Passed

**MOT #5** 2015-08-14 10:18**MOT test number** 569536525299**Result** ✗ Failed**Fail** Driver's door cannot be opened from inside the vehicle (6.2.B.1b)**MOT #4** 2014-03-20 12:33**MOT test number** 197119074403**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-03-19 14:57**MOT test number** 677048273040**Result** ✓ Passed**MOT #2** 2012-03-23 13:47**MOT test number** 428973982024**Result** ✓ Passed**MOT #1** 2011-03-22 14:18**MOT test number** 835371181005**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>ET570BC</b>
Plate since	2024-03-28
Current registration	 <b>ET570BC</b>
Plate since	2024-03-28

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-02-14
Last registration	2021-10-01
Complete history	<a href="#">See info</a>



Registration #1	2008-02-14	17 mi
Registration #2	2011-03-22	33.700 mi
Registration #3	2012-03-23	46.300 mi
Registration #4	2013-03-19	58.064 mi
Registration #5	2014-03-20	72.011 mi
Registration #6	2015-08-14	81.340 mi
Registration #7	2015-10-01	81.359 mi
Registration #8	2017-05-12	86.101 mi
Registration #9	2019-05-20	91.377 mi
Registration #10	2019-05-20	91.377 mi
Registration #11	2019-05-20	91.377 mi
Registration #12	2019-05-20	91.377 mi
Registration #13	2019-05-20	91.377 mi
Registration #14	2019-05-20	91.377 mi
Registration #15	2019-05-20	91.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141