





report date: 2024-03-29

# General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Black
Year of manufacture	2014
Top speed	151 mph
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



# Internet history

# Entry 1

Date 2021-08-21

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-31
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #10	2023-08-04 10:31
MOT test number	266167636014
Result	<b>✓</b> Passed
Next expiry date	2024-08-31
Advice Offside Front Suspension arm pin or bush worn but not resulting in extremely front lower front arm inner bush worn (5.3.4 (a) (i))	xcessive movement Offside

MOT #9	2023-07-21 14:52
MOT test number	951788178783
Result	<b>×</b> Failed
Fail  Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the indicate (ii))	gress of dirt (5.3.4 (b)
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Front Suspension arm pin or bush excessively worn Nearside front lower front arm inner bush badly split/worn (5.3.4 (a) (i))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excession front lower front arm inner bush worn (5.3.4 (a) (i))	ve movement Offside

MOT #8		2022-08-17 10:39
MOT test	number	893720315664
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Advice

LS14NXW report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2021-09-01 13:26
MOT test number	809179477332
Result	<b>✓</b> Passed
MOT #5	2021-03-12 07:44
MOT test number	615859204837
Result	✓ Passed
MOT #4	2020-06-09 14:20
MOT test number	528899897830
Result	✓ Passed
MOT #3	2019-03-29 15:16
MOT test number	754733436158
Result	✓ Passed
MOT #2	2018-03-29 10:51
MOT test number	868773223662
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-04-07 14:43

MOT test number 854202777219

**Result** ✓ Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	
********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NE N
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2023-08-04
Complete history	See info



Registration #1	2014-03-31	23 mi
Registration #2	2017-04-07	31.711 mi
Registration #3	2018-03-29	34.733 mi
Registration #4	2019-03-29	39.643 mi
Registration #5	2020-06-09	51.235 mi
Registration #6	2021-03-12	57.018 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.777-46

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	
iew the complete MERCEDES-BENZ factory list for this	More info >

# Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

# Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032265025

CarCheck.co.uk page 12/12