



General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Black
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-10
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	49
Total items failed	10

MOT #16 2023-08-08 13:58

MOT test number 584526187691

Result ✓ Passed

Next expiry date 2024-08-07

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Shock absorbers has a slightly worn bush TOP MOUNT MAKING NOISE (5.3.2 (c))
- Advice** Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2022-07-29 14:33

MOT test number 492727291720

Result ✓ Passed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2021-07-31 14:28

MOT test number 339719204837

Result ✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13**

2021-07-27 17:01

MOT test number

604425963951

Result

✗ Failed

- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12

2020-07-02 12:27

MOT test number

377948092924

Result

✓ Passed

- Advice** Front Shock absorbers light misting of oil or has limited damping effect nearside and offside (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases from flexi also rear box has corrosion (6.1.2 (a))

MOT #11

2019-07-06 14:36

MOT test number

525061449820

Result

✓ Passed

- Advice** Exhaust flexi damaged causing slight leak of exhaust gases, rear exhaust box corroded
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear nearside and offside tyres has slight cracks
- Advice** Front Shock absorbers light misting of oil or has limited damping effect nearside and offside (5.3.2 (b))

**MOT #10**

2018-07-24 12:15

MOT test number

882086715951

Result

✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Exhaust has a minor leak of exhaust gases flexible pipe area of (6.1.2 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9**

2018-07-24 12:15

MOT test number

937861348627

Result

✗ Failed

Pass with rectification Nearside Headlamp aim so that beam "kick up" is not visible on the screen no pattern (4.1.2 (a))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Exhaust has a minor leak of exhaust gases flexible pipe area of (6.1.2 (a))**MOT #8**

2017-07-20 09:16

MOT test number

529112947309

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Nail in tyre tyre**Advice** Undertrays fitted**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Front Exhaust has a minor leak of exhaust gases flexible pipe area of (7.1.2)

**MOT #7** 2017-07-20 09:16**MOT test number** 289617477261**Result** ✗ Failed**Advice** Undertrays fitted**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Front Exhaust has a minor leak of exhaust gases flexible pipe area of (7.1.2)**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect bulb fitted incorrectly (1.8.A.1b)**Advice** Offside Rear Nail in tyre tyre**MOT #6** 2016-07-11 09:28**MOT test number** 363922684829**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2016-07-11 07:50**MOT test number** 880303899628**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #4**

2015-07-09 12:47

MOT test number

709850795110

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Nail in nearside front tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyre's lightly perished**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #3**

2014-07-28 12:24

MOT test number

718109004204

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Nearside rear tyre wearing low on inner edge/slightly perished**Notice** Offside rear tyre below limit on inner edge

**MOT #2**

2014-07-28 10:50

MOT test number

525829104244

Result**✗ Failed**

- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Fail** Offside Front Braking system leaking (3.6.A.1)
- Notice** Nearside rear tyre wearing low on inner edge/slightly perished
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Notice** Offside rear tyre below limit on inner edge
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1

2013-05-10 16:55

MOT test number

267730633441

Result**✓ Passed**

- Notice** Both rear tyres bald on inner edges



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

✓

MOT

Expires:
7 August 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LT10TTV
Plate since	2024-03-29
Current registration	 LT10TTV
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2023-08-08
Complete history	See info



Registration #1	2010-05-28	7 mi
Registration #2	2013-05-10	23.139 mi
Registration #3	2014-07-28	38.176 mi
Registration #4	2014-07-28	38.176 mi
Registration #5	2015-07-09	49.372 mi
Registration #6	2016-07-11	60.069 mi
Registration #7	2016-07-11	60.071 mi
Registration #8	2017-07-20	66.754 mi
Registration #9	2017-07-20	66.754 mi
Registration #10	2018-05-28	75.277 mi
Registration #11	2018-05-28	75.277 mi
Registration #12	2018-05-28	75.277 mi
Registration #13	2018-05-28	75.277 mi
Registration #14	2018-05-28	75.277 mi
Registration #15	2018-05-28	75.277 mi
Registration #16	2018-05-28	75.277 mi
Registration #17	2018-05-28	75.277 mi
Registration #18	2018-05-28	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843