



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER COOPER
Colour	Silver
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	116 BHP
Max. torque	149 Nm at 4.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-10
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	62
Total items failed	3

MOT #21	2023-10-27 15:19
MOT test number	321833500225
Result	✓ Passed
Next expiry date	2024-10-26
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20**

2023-09-20 15:03

MOT test number

901911514023

Result**✗ Failed**

- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Brake pipe excessively corroded front to rear at rear (1.1.11 (c))
- MAJOR** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- MAJOR** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear in middle (1.1.11 (c))
- MAJOR** Nearside Front Tyre not fitted in accordance with side wall instructions rotation (5.2.3 (i))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #19

2022-05-03 14:12

MOT test number

467920639488

Result**✓ Passed**

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #18**

2021-05-20 09:05

MOT test number

221087716622

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**MOT #17**

2021-05-12 11:12

MOT test number

408249576036

Result

✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement slight play in rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush on bottom arm (5.3.4 (a) (i))**Minor** Front Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16**

2020-03-06 10:17

MOT test number

395324696948

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Brake pipe corroded, covered in grease or other material front to rear corroding in clips (1.1.11 (c))

**MOT #15**

2019-03-07 12:06

MOT test number

849957929790

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Fluid leak, but not excessive coolant leak from radiator (8.4.1 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material front to rear brake pipes corroding in clips (1.1.11 (c))**MOT #14**

2018-03-23 15:22

MOT test number

903969549417

Result

✓ Passed

Advice Brake pipe slightly corroded front to rear brake pipe corroded in clips (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #13**

2018-03-23 09:48

MOT test number

538651028532

Result

✗ Failed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Brake pipe slightly corroded front to rear brake pipe corroded in clips (3.6.B.2c)**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #12**

2017-03-31 07:54

MOT test number

443089447269

Result

✓ Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Coolant leak**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2017-03-29 08:49

MOT test number

669907522051

Result

✗ Failed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Coolant leak

MOT #10

2016-03-11 16:49

MOT test number

368493594665

Result

✓ Passed

- Advice** Nearside Rear metal brake pipe to flexi starting to corrode
- Advice** Rear brake pads wearing low
- Advice** Both front to rear metal brake pipes starting to corrode in the mount clips
- Advice** Offside Rear metal brake pipe to flexi starting to corrode

MOT #9

2015-03-30 09:14

MOT test number

889739085089

Result

✓ Passed

- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2014-03-26 12:03**MOT test number** 306275584042**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Centre main brake pipe slightly corroded
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Notice** Rear exhaust box corroded
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2013-03-15 09:43**MOT test number** 565904473065**Result** ✓ Passed

- Notice** Rear exhaust corroded

MOT #6 2012-03-09 10:30**MOT test number** 847089862020**Result** ✓ Passed**MOT #5** 2011-03-23 15:17**MOT test number** 329642381053**Result** ✓ Passed



MOT #4	2010-03-08 09:00
---------------	------------------

MOT test number	921337960008
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	N/side front tyre void of tread on outer edge.
---------------	--

Notice	Small scew in tread of the rear o/side tyre.
---------------	--

Notice	O/side front tyre wearing on outer edge.
---------------	--

MOT #3	2009-03-25 11:27
---------------	------------------

MOT test number	160564189057
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2008-03-28 09:40
---------------	------------------

MOT test number	862978788009
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-03-21 10:40
---------------	------------------

MOT test number	272830687050
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
17 April 2024

✓

MOT

Expires:
26 October 2024

Tax status	Expired at 17 April 2024
Days left	12 days too late
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-29
Last registration	2023-10-27
Complete history	See info



Registration #1	2004-03-29	25 mi
Registration #2	2007-03-21	21.378 mi
Registration #3	2008-03-28	28.529 mi
Registration #4	2009-03-25	31.939 mi
Registration #5	2010-03-08	34.916 mi
Registration #6	2011-03-23	36.368 mi
Registration #7	2012-03-09	38.746 mi
Registration #8	2013-03-15	40.558 mi
Registration #9	2014-03-26	45.160 mi
Registration #10	2015-03-30	49.409 mi
Registration #11	2016-03-11	53.106 mi
Registration #12	2017-03-29	57.333 mi
Registration #13	2018-03-29	59.333 mi
Registration #14	2019-03-29	61.333 mi
Registration #15	2020-03-29	63.333 mi
Registration #16	2021-03-29	65.333 mi
Registration #17	2022-03-29	67.333 mi
Registration #18	2023-03-29	69.333 mi
Registration #19	2024-03-29	71.333 mi
Registration #20	2025-03-29	73.333 mi
Registration #21	2026-03-29	75.333 mi
Registration #22	2027-03-29	77.333 mi
Registration #23	2028-03-29	79.333 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1925 mm
Height	1408 mm
Length	3626 mm
Wheel base	2467 mm
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	D495R294