



report date: 2024-03-29

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Black
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-11-06
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	42
Total items failed	23

MOT #12	2023-12-08 10:37
MOT test number	275161864231
Result	✓ Passed
Next expiry date	2024-12-07

**MOT #11**

2023-11-22 14:08

MOT test number

888736152408

Result**✗ Failed**

Fail Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt INNER REAR COVER (5.3.4 (b) (ii))

Fail Nearside Rear Lower Suspension rod ball joint dust cover no longer prevents the ingress of dirt rear adjusting arm (5.3.4 (b) (ii))

Advice Offside Rear Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Offside Headlamp lens seriously defective (4.1.1 (b) (ii))

Fail Nearside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt OUTER JOINT COVER AND EXCESSIVELY WORN (5.3.4 (b) (ii))

Fail Offside Rear Lower Suspension rod ball joint dust cover no longer prevents the ingress of dirt rear adjusting arm (5.3.4 (b) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Nearside Rear Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt OUTER JOINT COVER AND EXCESSIVELY WORN (5.3.4 (b) (ii))

Fail Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10**

2022-11-17 09:03

MOT test number

902936349135

Result

✓ Passed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Suspension rod ball joint dust cover severely deteriorated And corroded (5.3.4 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Offside Rear Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Rear Suspension rod ball joint dust cover severely deteriorated And corroded (5.3.4 (b) (i))

**MOT #9**

2022-11-16 17:02

MOT test number

209202315510

Result

✗ Failed

Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Rear Suspension rod ball joint dust cover severely deteriorated And corroded (5.3.4 (b) (i))**Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Nearside Rear Suspension rod ball joint dust cover severely deteriorated And corroded (5.3.4 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8**

2021-11-09 14:47

MOT test number

489847992688

Result

✓ Passed

Advice Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement offside & nearside (5.3.4 (a) (i))**Advice** Nearside Rear Upper Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #7**

2021-03-18 15:58

MOT test number

687036613657

Result

✓ Passed

**MOT #6** 2021-03-15 16:45**MOT test number** 437299545136**Result** ✗ Failed

- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Offside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Nearside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #5 2020-03-17 08:21**MOT test number** 297446268901**Result** ✓ Passed

- Advice** Advise slight play at both rear hubs
- Advice** Advise power steering pipes to rack corroded
- Advice** Advise bushes starting to perish on rear tie rods

MOT #4 2020-03-12 11:50**MOT test number** 907098395743**Result** ✗ Failed

- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Advice** Advise bushes starting to perish on rear tie rods
- Advice** Advise power steering pipes to rack corroded
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Advise slight play at both rear hubs

**MOT #3** 2019-03-04 12:59**MOT test number** 604412497937**Result** ✓ Passed

- Advice** Tyre wear/cracking
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central exhaust heatshield loose
- Advice** Rear Fuel Pipe/s corroded

MOT #2 2019-03-04 11:01**MOT test number** 956121599508**Result** ✗ Failed

- Advice** Tyre wear/cracking
- Advice** Rear Fuel Pipe/s corroded
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Central exhaust heatshield loose
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #1 2017-11-28 16:00**MOT test number** 478735899459**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	OX06XHZ
Plate since	2024-03-29
Current registration	OX06XHZ
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2006-07-31
Last registration	2023-12-08
Complete history	See info



Registration #1	2006-07-31	8 mi
Registration #2	2017-11-28	98.867 mi
Registration #3	2019-03-04	101.589 mi
Registration #4	2019-03-04	101.589 mi
Registration #5	2020-03-12	103.585 mi
Registration #6	2020-03-17	103.598 mi
Registration #7	2021-03-15	104.806 mi
Registration #8	2023-12-08	105.277 mi
Registration #9	2023-12-08	105.277 mi
Registration #10	2023-12-08	105.277 mi
Registration #11	2023-12-08	105.277 mi
Registration #12	2023-12-08	105.277 mi
Registration #13	2023-12-08	105.277 mi
Registration #14	2023-12-08	105.277 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G