





report date: 2024-03-28

General information

Make	FORD
Model	C-MAX STYLE 125
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP	
Max. torque	165 Nm at 4.000 rpm	
Engine capacity	1.798 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	29.4 mpg	
Consumption extra urban	50.4 mpg	
Consumption combined	39.8 mpg	
CO2 emission	169 g/km	
CO2 label	Н	



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-19
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	27
Total items failed	6

MOT #16	2023-06-20 09:34
MOT test number	420934383811
Result	✓ Passed
Next expiry date	2024-06-19
Advice Nearside Rear Outer Brake disc worn, pitted or scored, but not seriousl corrosion (1.1.14 (a) (ii))	ly weakened Surface has
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Front Clutch pedal anti slip provision missing (rubber)	
Advice Offside Rear Outer Brake disc worn, pitted or scored, but not seriously corrosion (1.1.14 (a) (ii))	weakened Surface has
Advice Nearside Front Outer Brake disc worn, pitted or scored, but not seriously weakened Surface has corrosion (1.1.14 (a) (ii))	
Advice Offside Front Outer Brake disc worn, pitted or scored, but not seriously corrosion (1.1.14 (a) (ii))	weakened Surface has
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15 2023-06-19 14:35

MOT test number 458700743192

Result X Failed

Advice Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened Surface has corrosion (1.1.14 (a) (ii))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Outer Brake disc worn, pitted or scored, but not seriously weakened Surface has corrosion (1.1.14 (a) (ii))

Advice Offside Front Outer Brake disc worn, pitted or scored, but not seriously weakened Surface has corrosion (1.1.14 (a) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Clutch pedal anti slip provision missing (rubber)

Advice Nearside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened Surface has corrosion (1.1.14 (a) (ii))

MOT #14 2022-01-21 13:40

MOT test number 973755367608

Result

✓ Passed

MOT #13 2022-01-21 13:40

MOT test number 456330185805

Result X Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12 2020-12-15 10:44

MOT test number 470958091036

Advice Hand brake travel

Advice Clutch pedal rubber missing

CarCheck.co.uk page 4/13



report date: 2024-03-28

✓ Passed

MOT #11 2020-01-21 13:34

188713039802 **MOT** test number

Result ✓ Passed

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2019-01-08 09:57

MOT test number 345190692706

Result ✓ Passed

MOT #9 2019-01-08 09:57

MOT test number 157492321626

Result × Failed

Pass with rectification Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

Pass with rectification Registration plate lamp does not illuminate simultaneously with the position

lamps BOTH (4.7.2 (a))

MOT test number

Result

MOT #8 2018-01-08 09:37 **MOT** test number 297282494218

Result ✓ Passed

MOT #7 2017-01-11 09:46

MOT test number 356890642131

Result ✓ Passed

MOT #6 2016-01-25 10:24

MOT test number 617851231222

Result Passed

MOT #5 2015-04-28 11:47

258848615430

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2013-04-08 10:04

MOT test number 498678693080

Result ✓ Passed

MOT #2

MOT test number

648849532047

Result

Notice Slight damage nearside front tyre wall

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Both offside front and nearside rear tyre walls scuffed

Advice Offside Rear reflector slightly damaged but function not impaired (1.5.1c)

 MOT #1
 2012-02-08 13:44

 MOT test number
 987129032007

Result X Failed

Pass with rectification Offside Rear Wheel nut(s) missing (4.2.A.1e)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Obligatory mirror insecure (8.1.1)

Notice Both offside front and nearside rear tyre walls scuffed

Advice Offside Rear reflector slightly damaged but function not impaired (1.5.1c)

Notice Slight damage nearside front tyre wall

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

α	vner	hi	ctc	1
\cup	viiei	ш	SIL	ע ונ

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>better</u>		ave?
manage of the same		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		, ,
Current registration	UK MIN	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-02-17
Last registration	2023-06-20
Complete history	See info



Registration #1	2009-02-17	9 mi
Registration #2	2012-02-08	27.721 mi
Registration #3	2013-04-08	30.600 mi
Registration #4	2014-04-24	32.295 mi
Registration #5	2015-04-28	36.723 mi
Registration #6	2016-01-25	43.206 mi
Registration #7	2017-01-11	44.487 mi
Registration #8	2018-01-08	46.773 mi
Registration #9	2019-01-08	47.679 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1409 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 9U67475