



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA FLARE
Colour	Blue
Year of manufacture	2006
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-06
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-02
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	34
Total items failed	3

MOT #18	2023-08-03 14:22
MOT test number	405534064764
Result	✓ Passed
Next expiry date	2024-08-02
Advice	Exhaust bracket broken
Advice	Oil leak from engine
Advice	Front tyres worn and perished

MOT #17	2022-07-22 11:44
MOT test number	868354449995
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Both front tyres deteriorating

MOT #16	2021-08-03 13:49
MOT test number	410372692877
Result	✓ Passed

**MOT #15**

2020-10-26 15:11

MOT test number

667780776851

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin N.S and O.S (1.1.13 (a) (ii))
- Advice** Exhaust system has slight corrosion
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing slight cracking between tread (5.2.3 (d) (ii))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Engine auxiliary belt slight worn and cracking
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing slight cracking between tread (5.2.3 (d) (ii))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2019-10-14 15:37

MOT test number

365382069633

Result

✓ Passed

- Advice** Advise exhaust system corroded.
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Advise engine alternator belt worn and splitting.
- Advice** Both front headlamps perished.
- Advice** Nearside Rear brakes binding slightly.

**MOT #13** 2019-10-14 14:42**MOT test number** 233734150897**Result** ✗ Failed**Advice** Advise exhaust system corroded.**Advice** Advise engine alternator belt worn and splitting.**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure perished to cords (5.2.3 (d) (ii))**Advice** Both front headlamps perished.**Advice** Nearside Rear brakes binding slightly.**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect bulb may be fitted wrong. (4.1.2 (c))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure perished to cords (5.2.3 (d) (ii))**MOT #12** 2018-10-16 15:50**MOT test number** 124669215947**Result** ✓ Passed**MOT #11** 2017-09-27 14:36**MOT test number** 790893619592**Result** ✓ Passed**MOT #10** 2016-09-28 07:51**MOT test number** 918957687491**Result** ✓ Passed**MOT #9** 2015-10-19 14:44**MOT test number** 572440187466**Result** ✓ Passed

**MOT #8** 2014-10-27 17:20**MOT test number** 855700404395**Result** ✓ Passed**Notice** Small cut in n/s/f sidewall**MOT #7** 2013-10-15 10:40**MOT test number** 218678983297**Result** ✓ Passed**Notice** Rear exhaust flange corroded**Notice** N/s/f sidewall scrubbbed**MOT #6** 2012-10-29 13:14**MOT test number** 458703102471**Result** ✓ Passed**MOT #5** 2011-10-31 12:06**MOT test number** 829754901320**Result** ✓ Passed**MOT #4** 2011-10-31 12:06**MOT test number** 999904601342**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2010-11-02 11:14**MOT test number** 610856300391**Result** ✓ Passed



MOT #2	2010-11-02 11:14
MOT test number	230946800330
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2009-11-02 14:53
MOT test number	481876909312
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-11-02
Last registration	2023-08-03
Complete history	See info



Registration #1	2006-11-02	20 mi
Registration #2	2009-11-02	14.344 mi
Registration #3	2010-11-02	17.225 mi
Registration #4	2011-10-31	20.614 mi
Registration #5	2012-10-29	23.719 mi
Registration #6	2013-10-15	26.394 mi
Registration #7	2014-10-27	29.124 mi
Registration #8	2015-10-19	31.565 mi
Registration #9	2016-09-28	34.125 mi
Registration #10	2016-09-28	34.125 mi
Registration #11	2016-09-28	34.125 mi
Registration #12	2016-09-28	34.125 mi
Registration #13	2016-09-28	34.125 mi
Registration #14	2016-09-28	34.125 mi
Registration #15	2016-09-28	34.125 mi
Registration #16	2016-09-28	34.125 mi
Registration #17	2016-09-28	34.125 mi
Registration #18	2016-09-28	34.125 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1482 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	448099