



report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Black
Year of manufacture	2007
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	32
Total items failed	15

MOT #20	2024-02-12 16:13
MOT test number	759380247788
Result	✓ Passed
Next expiry date	2025-02-13
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19	2024-02-12 16:13
MOT test number	326627007931
Result	✗ Failed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #18**

2023-02-14 15:46

MOT test number

375287232085

Result

✓ Passed

- Advice** Under vehicle and components has corrosion around
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Fuel Pipe/s corroded

MOT #17

2021-08-18 10:20

MOT test number

544590641905

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Underside has surface rust
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16

2020-08-21 12:15

MOT test number

278317415936

Result

✓ Passed

- Advice** Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

**MOT #15** 2020-08-20 15:05**MOT test number** 874990815960**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))**MOT #14** 2019-07-21 14:14**MOT test number** 615536093648**Result** ✓ Passed**MOT #13** 2019-07-20 10:59**MOT test number** 903590818698**Result** ✗ Failed**Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Front Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Rear Brake cable insecure (1.1.15 (c))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #12** 2018-08-10 11:26**MOT test number** 584269851602**Result** ✓ Passed

**MOT #11** 2017-07-25 14:50**MOT test number** 335753466765**Result** ✓ Passed**Advice** Offside mirror cover damaged**Advice** Offside Oil leak drive shaft seal**Advice** Front grille insecure**MOT #10** 2017-07-25 08:25**MOT test number** 952438610033**Result** ✗ Failed**Advice** Offside mirror cover damaged**Fail** Rear registration plate faded (6.3.1d)**Fail** Offside Front Brake pipe excessively corroded part of flexi section (3.6.B.2c)**Advice** Front grille insecure**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Oil leak drive shaft seal**MOT #9** 2016-02-19 10:19**MOT test number** 903828868510**Result** ✓ Passed**Advice** Rear tyre treads getting low**Advice** Rear registration plate deteriorating

**MOT #8** 2016-02-19 10:19**MOT test number** 546657612257**Result** ✗ Failed**Advice** Rear tyre treads getting low**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear registration plate deteriorating**MOT #7** 2015-02-03 16:12**MOT test number** 179394135437**Result** ✓ Passed**MOT #6** 2013-12-12 12:10**MOT test number** 895176343312**Result** ✓ Passed**MOT #5** 2013-12-11 10:53**MOT test number** 449665743419**Result** ✗ Failed**Notice** High level brake light inop**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2012-12-11 11:26**MOT test number** 659736942382**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #3 2011-12-07 16:11

MOT test number 336621041312

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #2 2011-12-07 10:45

MOT test number 686841641310

Result ✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #1 2010-12-16 11:02

MOT test number 463820550409

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
13 February 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-10
Last registration	2024-02-12
Complete history	See info



Registration #1	2007-12-10	19 mi
Registration #2	2010-12-16	16.913 mi
Registration #3	2011-12-07	23.373 mi
Registration #4	2011-12-07	23.373 mi
Registration #5	2012-12-11	34.280 mi
Registration #6	2013-12-11	46.866 mi
Registration #7	2013-12-12	46.891 mi
Registration #8	2015-02-03	48.631 mi
Registration #9	2016-02-19	56.523 mi
Registration #10	2016-02-19	56.523 mi
Registration #11	2017-07-25	72.124 mi
Registration #12	2019-05-20	95.557 mi
Registration #13	2019-05-20	95.557 mi
Registration #14	2019-05-20	95.557 mi
Registration #15	2019-05-20	95.557 mi
Registration #16	2019-05-20	95.557 mi
Registration #17	2019-05-20	95.557 mi
Registration #18	2019-05-20	95.557 mi
Registration #19	2019-05-20	95.557 mi
Registration #20	2019-05-20	95.557 mi
Registration #21	2019-05-20	95.557 mi
Registration #22	2019-05-20	95.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7L05452