





General information Make CITROEN Model GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO Colour Purple Year of manufacture 2009 **Top speed** 112 mph 0 - 60 mph 12.7 seconds Gearbox 5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F







Internet history

Entry 1	
Date	2021-09-04
Pictures	45
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-14
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	26
Total items failed	8

MOT #16 2	2022-02-10 16:23
MOT test number	772063042483
Result	✓ Passed
Next expiry date	2023-02-14
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3	(e))

MOT #15			2022-02-09 10:12
MOT test	umber		939166088626
Result			× Failed
MAJOR	Parking brake inope	rative on one side (1.4.1 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))			
MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))			
MAJOR	Electronic parking bi	rake control defective so that i	t cannot be satisfactorily operated (1.1.6 (d))
DANGER	US Nearside Real	r Brake pad(s) less than 1.5 m	m thick (1.1.13 (a) (ii))
DANGER	DUS Parking brake	e efficiency less than 50% of th	e required value (1.4.2 (a) (ii))
MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))			





MOT #14		2021-02-01 14:44
MOT test nu	nber	586341072048
Result		✓ Passed
Minor Re	gistration plate lamp inoperative in the case of multiple lamps or light source	as (4.7.1 (b) (i))
MOT #13		2020-01-29 11:03
MOT test nu	nber	364893410305
Result		✓ Passed
MOT #12		2020-01-27 12:50
MOT test nu	nber	729990469171
Result		🗙 Failed
DANGEROU	US Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROL	IS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MOT #11		2019-02-06 13:56
MOT test nu	nber	906165511507
Result		✓ Passed



RV09EGZ report date: 2024-03-28

MOT #10		2019-02-05 13:38
MOT test	number	523882497264
Result		🗙 Failed
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a))	
MAJOR	Nearside Headlamp aim not tested (4.1.2 (b))	
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sour	rces (4.7.1 (b) (i))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))	
DANGEI (d) (ii))	ROUS Nearside Rear Tyre has a lump, caused by separation or partial failure	e of its structure (5.2.3
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #9		2018-02-05 12:36
MOT test i	number	227808824674
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2017-02-15 16:26
MOT test number	747266007133
Result	✓ Passed





MOT #7	2016-02-15 16:05
MOT test number	682994763404
Result	✓ Passed
MOT #6	2016-02-15 13:05
MOT test number	967958172095
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

2015-02-05 16:11
187896035098
✓ Passed

MOT #4	2014-02-27 16:10
MOT test number	396408554062
Result	✓ Passed

МОТ #3	2013-03-19 17:14
MOT test number	539528973038
Result	✓ Passed

MOT #2	2012-08-07 16:51
MOT test number	608980422294
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	





MOT #1	2012-08-07 12:51
MOT test number	306650922458
Result	🗙 Failed
Fail Nearside Headlamp aim too low (1.8)	
FailRear registration plate deteriorated (6.3.1d)	
FailBrake pedal anti-slip provision missing (3.3.A.1b)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

X Untaxed Tax expired: 7 October 2022	X MOT Expired: 14 February 2023
Tax status	Expired at 7 October 2022
Days left	570 days too late
MOT expiry date	14 February 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-08-12
Last registration	2022-02-10
Complete history	See info



Registration #1	2009-08-12	24 mi
Registration #2	2012-08-07	29.633 mi
Registration #3	2012-08-07	29.633 mi
Registration #4	2013-03-19	31.855 mi
Registration #5	2014-02-27	39.530 mi
Registration #6	2015-02-05	45.549 mi
Registration #7	2016-02-15	50.908 mi
Registration #8	2016-02-15	50.908 mi
Registration #9	2017-02-15	55.899 mi
Registration #10		11.777 est
Registration #11		11.707 est
Registration #12		11.777 est
Registration #13		11.707 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		10. 100 aug





Safety ratings		
NCAP rating		
Video	see crash video	
Dimensions & weight		
Width		1829 mm
Height		1700 mm
Length		4585 mm
Wheel base		2728 mm
Kerb weight		1530 kg
Max. allowed weight		2250 kg
Additional information		
Fuel tank capacity		60 I
Fuel delivery		Direct Injection
Number of doors		5
Number of seats		7
Number of axles		2
Engine number		JBCV0048476