





# General information

Make	CITROEN
Model	C5 HDI VTR PLUS
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С





Internet history			
Entry 2			
Date	2022-10-1	0	
Pictures	9		
Listing price	View repor	<u>t</u>	
	<section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header>		
source: cargurus.co.uk			
Entry 1	2022.02.0	c	
Date	2022-03-0	6	
Pictures	12		
Listing price	View repor	<u>t</u>	



source: cargurus.co.uk









# MOT history

MOT expiry date	2025-01-12
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #10	2024-01-13 14:32
MOT test number	237645024757
Result	✓ Passed
Next expiry date	2025-01-12
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	

МОТ #9	2022-12-12 13:00
MOT test number	698817802021
Result	✓ Passed

MOT #8	2022-01-25 09:03
MOT test number	174020940751
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-01-26 09:43
MOT test number	869551846879
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	





МОТ #6	2020-01-20 09:46
MOT test number	474955982724
Result	✓ Passed
MinorNearside Front Windscreen damaged but not adversely affecting driver'sAdviceOffside Rear Child Seat fitted not allowing full inspection of adult belt	view (3.2 (a) (i))

MOT #5	2019-01-28 09:20
MOT test number	562149669200
Result	✓ Passed

MOT #4	2019-01-26 13:42
MOT test number	864856194353
Result	🗙 Failed
Fail         Nearside Front Tyre tread depth below requirements of 1.6mm (5.2)	2.3 (e))
Fail         Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3)	3 (e))
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.)	3 (e))

# MOT #32018-06-27 08:30MOT test number189941068844ResultImage: Constant of the state of the stat

MOT #2	2017-06-27 11:26
MOT test number	767793041699
Result	✓ Passed





MOT #1		2017-06-27 11:26
MOT test number		892786512338
Result		🗙 Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

<b>Tax due:</b> 1 March 2025	√ Taxed	✓ MOT Expires: 12 January 2025
Tax status		Valid until 1 March
Days left		30
MOT expiry date		12 January 202
Full MOT history		See MOT histor
Tax calculation		

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

4
AMP
- A

### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 11.111
Average private trade value	4 10 200





# Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-24
Last registration	2024-01-13
Complete history	See info



Registration #1	2014-07-24	24 mi
Registration #2	2017-06-27	58.826 mi
Registration #3	2017-06-27	58.826 mi
Registration #4	2018-06-27	78.823 mi
Registration #5	2019-01-26	82.639 mi
Registration #6	2019-01-28	82.639 mi
Registration #7	2020-01-20	91.942 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 esi





# Safety ratings

NCAP rating	****
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight	
Width	1860 mm
Height	1512 mm
Length	4829 mm
Wheel base	2815 mm
Kerb weight	1537 kg
Max. allowed weight	2153 kg
Additional information	
Additional information Fuel tank capacity	71
	71 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5