



General information

Make	VOLVO
Model	S40 S S40
Colour	Black
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-06-23
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	17
Total items failed	12
MOT #19	2023-06-10 11:02
MOT test number	145757807536
Result	✓ Passed
Next expiry date	2024-06-22
MOT #18	2022-06-21 07:26
MOT test number	102757210441
Result	✓ Passed
MOT #17	2021-06-23 16:01
MOT test number	683505986080
Result	✓ Passed
MOT #16	2020-06-23 09:05
MOT test number	119281154561
Result	✓ Passed
MOT #15	2019-04-27 08:04
MOT test number	704418200149
Result	✓ Passed

**MOT #14** 2018-10-18 13:46**MOT test number** 840820958783**Result** ✓ Passed

- Advice** Nearside Rear handbrake cable nipple
- Advice** Nearside Rear hand brake cable nipple corroding
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear handbrake cable nipple
- Advice** Offside Rear hand brake cable nipple

MOT #13 2018-10-13 10:32**MOT test number** 253688212245**Result** ✗ Failed

- Advice** Nearside Rear hand brake cable nipple corroding
- Advice** Offside Rear handbrake cable nipple
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear hand brake cable nipple
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear handbrake cable nipple
- Fail** Oil leaking excessively from transmission Driveshaft seal (8.4.1 (a) (i))

MOT #12 2017-10-12 09:01**MOT test number** 457203400685**Result** ✓ Passed

- Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #11** 2017-10-12 09:01**MOT test number** 694010928447**Result** ✗ Failed

Pass with rectification Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

Pass with rectification Headlamp aim too low (1.8)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #10 2016-09-27 11:41**MOT test number** 467763110052**Result** ✓ Passed**MOT #9** 2016-09-26 16:05**MOT test number** 303940241495**Result** ✗ Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #8 2015-09-10 10:27**MOT test number** 263354123924**Result** ✓ Passed

Advice Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #7 2014-10-09 10:17**MOT test number** 237992084204**Result** ✓ Passed

**MOT #6** 2014-10-09 10:17**MOT test number** 278822284290**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2013-09-13 13:20**MOT test number** 367346553273**Result** ✓ Passed**Notice** Both front tyres wearing thin mid tread**MOT #4** 2012-08-30 12:03**MOT test number** 465003442271**Result** ✓ Passed**MOT #3** 2012-08-30 12:03**MOT test number** 937263642204**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low and too far to the left. (1.8)**MOT #2** 2011-07-11 14:01**MOT test number** 727652591169**Result** ✓ Passed



MOT #1	2011-07-11 10:51
MOT test number	155992391147
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
22 June 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-08-11
Last registration	2023-06-10
Complete history	See info



Registration #1	2008-08-11	29 mi
Registration #2	2011-07-11	34.527 mi
Registration #3	2011-07-11	34.528 mi
Registration #4	2012-08-30	42.909 mi
Registration #5	2013-09-13	50.636 mi
Registration #6	2014-10-09	57.893 mi
Registration #7	2015-09-10	64.137 mi
Registration #8	2016-09-26	71.385 mi
Registration #9	2016-09-27	71.386 mi
Registration #10	2017-10-12	86.027 mi
Registration #11	2018-06-20	95.377 mi
Registration #12	2019-06-20	105.377 mi
Registration #13	2020-06-20	115.377 mi
Registration #14	2021-06-20	125.377 mi
Registration #15	2022-06-20	135.377 mi
Registration #16	2023-06-20	145.377 mi
Registration #17	2024-06-20	155.377 mi
Registration #18	2025-06-20	165.377 mi
Registration #19	2026-06-20	175.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number

131943