





report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Red
Year of manufacture	2015
Top speed	100 mph
0 - 60 mph	14.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-08-12

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-02-03	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-27
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #8		2023-09-28 16:13
MOT test	number	714206751555
Result		✓ Passed
Next expi	ry date	2024-09-27
Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7		2023-09-28 10:44
MOT test	number	908506049227
Result		X Failed
MAJOR	Nearside Rear Service brake grabbing severely (1.2.1 (c))	
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or co	ords (5.2.3 (d) (i))
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MAJOR	Offside Rear Service brake grabbing severely (1.2.1 (c))	
Minor	Front Windscreen wiper blade defective o/s and n/s (3.4 (b) (i))	

CarCheck.co.uk page 3/12



MOT #6 2022-09-03 10:06

MOT test number 536055669100

Result ✓ Passed

Minor Offside Rear Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))

Advice Rear Service brake binding but not excessively Both sides. Advise rear brake service. (1.2.1 (f))

MOT #5 2021-09-08 16:19

MOT test number 516774514936

Result ✓ Passed

MOT #4 2019-05-23 15:31

MOT test number 460013385954

Result \(\sqrt{Passed} \)

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #3 2019-05-23 08:35

MOT test number 922459769168

Result X Failed

Advice Vehicles internal headlight adjuster altered to recheck lights

MAJOR Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt

MAJOR Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



MOT #2

MOT test number

Result

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Rear Nail in tyre

MOT #1 2018-05-25 08:27 **MOT** test number 551977640589 Result **X** Failed Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Nail in tyre Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union mestery	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes See in this check if this NISSAN had different number plates.	
See in this check if this Missain had different humber plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-29
Last registration	2023-09-28
Complete history	See info



Registration #1	2015-05-29	9 mi
Registration #2	2018-05-25	28.047 mi
Registration #3	2018-05-25	28.047 mi
Registration #4	2019-05-23	36.055 mi
Registration #5	2019-05-23	36.055 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1535 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	945 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 769327B