





report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 2
Colour	Black
Year of manufacture	2015
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 4

Date 2024-03-13


Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 3

Date	2022-02-24
------	------------


Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2022-02-24

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Pictures 20

Listing price <u>View report</u>









source: yesauto.com



report date: 2024-03-28

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2025-03-17
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #10	2024-03-18 13:27
MOT test number	397739414108
Result	✓ Passed
Next expiry date	2025-03-17

MOT #9		2023-02-27 16:14
MOT test i	number	902074665753
Result		✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Tpms light on	

MOT #8	2022-02-23 20:38
MOT test number	401508203498
Result	✓ Passed
Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))	

MOT #7	2021-05-19 14:44
MOT test number	527066146522
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number
973624553640

Result
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT test number

512432340297

Result

X Failed

Fail Nearside Front Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Front Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4		2019-06-25 15:09
MOT test	number	100219151961
Result		✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-06-20 12:39 518868593201 **MOT** test number Result × Failed **Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail

MOT #2

MOT test number

117822471115

Result

✓ Passed

MOT test number

Result

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 5/12



EF15XOW report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	
manners .	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-07-06
Last registration	2024-03-18
Complete history	See info



Registration #1	2015-07-06	20 mi
Registration #2	2018-07-03	34.494 mi
Registration #3	2018-07-03	34.494 mi
Registration #4	2019-06-20	42.618 mi
Registration #5	2019-06-25	42.694 mi
Registration #6	2020-07-22	47.431 mi
Registration #7	2020-07-24	47.457 mi
Registration #8	2021-05-19	53.481 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1509 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number D4FBFZ638572