

Ford



## General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 L LWB P/V 90
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 сс
Cylinders	4
Fuel type	Diesel





# MOT history

MOT expiry date	2021-01-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	13
Total items failed	20

MOT #13	2020-01-23 11:32
MOT test number	635528390285
Result	🗸 Passed
Next expiry date	2021-01-22
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2020-01-20 11:13
MOT test number	627816700207
Result	🗙 Failed
<b>Fail</b> Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))	
<b>Fail</b> Front Exhaust has a major leak of exhaust gases (6.1.2 (a))	
<b>Minor</b> Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
FailNearside Rear Registration plate lamp inoperative in the case of a single lamp or(ii))	all lamps (4.7.1 (b)
<b>Fail</b> Nearside Rear Suspension component mounting prescribed area excessively correducing structural strength outer sill (5.3.6 (a) (i))	roded significantly



REOSUPY report date: 2024-03-29

MOT #3	11	2019-01-22 12:03
MOT te	st number	263397560845
Result		✓ Passed
MOT #3	10	2019-01-21 09:04
MOT te	st number	246817506702
Result		× Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> ingress	Nearside Front Drive shaft joint constant velocity boot split or insecure, no long of dirt $(6.1.7 (g) (ii))$	ger prevents the
Fail	Nearside Front Position lamp not working (4.2.1 (a))	
Fail	Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Fail	<b>Fail</b> Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail	Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))	
Fail	Central Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail	Offside Front Position lamp not working (4.2.1 (a))	

MOT #9	2017-11-29 11:08
MOT test number	216432841212
Result	✓ Passed



<b>RE08UPY</b>
report date: 2024-03-29

🗸 Passed

MOT #8		2016-12-01 17:25
MOT test	number	112487117837
Result		✓ Passed
Advice	Nsr tyre perishing	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
<b>Advice</b> (2.5.C.1a)	Offside Front Inner Front constant velocity joint gaiter damaged, but prev	venting the ingress of dirt
MOT #7		2015-12-02 10:03
MOT test	number	372457872764

Result

MOT #6		2015-12-02 10:03
MOT test number		273246586245
Result		🗙 Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	
Pass with rectification	Centre Stop lamp not working (1.2.1b)	

MOT #5	2014-11-19 11:31
MOT test number	326273424313
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal lim	it (4.1.E.1)
Notice Oil leak	

MOT #4		2013-08-28 15:54
MOT test	number	446210443200
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (	8.3.1d)





MOT #3	2013-08-27 11:58	
MOT test number	269789533259	
Result	🗙 Failed	
Fail Nearside Inner Front constant velocity joint is excessively worn (2.5.C.1b)		
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		
MOT #2	2012-08-13 12:38	
MOT test number	727216222230	
Result	✓ Passed	
MOT #1	2011-05-27 11:09	

MOT test number	429987141162
Result	✓ Passed



REOSUPY report date: 2024-03-29

Tax & MOT check

X Untaxed	Х MOT
Tax expired: 1 April 2021	Expired: 22 January 2021
Tax status	Expired at 1 April 2021
Days left	1124 days too late
MOT expiry date	22 January 2021
Full MOT history	See MOT history





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



REOSUPY report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-05-27
Last registration	2020-01-23
Complete history	See info



Registration #1	2008-05-27	15 mi
Registration #2	2011-05-27	30.026 mi
Registration #3	2012-08-13	42.157 mi
Registration #4	2013-08-27	55.355 mi
Registration #5	2013-08-28	55.355 mi
Registration #6	2014-11-19	66.040 mi
Registration #7	2015-12-02	74.291 mi
Registration #8		10.200 and
Registration #9		11.777 mi
-		11.227 est
Registration #9		11.222 est 11.222 est 11.222 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 0.000 est 00.000 est





### Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

## Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	8R08832