





report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI SE
Colour	Blue
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	141 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history


Entry 1

Date 2021-06-15

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2023-05-30
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #13	2022-05-31 13:41
MOT test number	789266691169
Result	✓ Passed
Next expiry date	2023-05-30
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #12	2021-05-25 13:02
MOT test number	703164923447
Result	✓ Passed

MOT #11		2021-05-25 13:02
MOT test number		239823395732
Result		🗙 Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2020-06-23 08:56 683182504924 **MOT** test number ✓ Passed Result **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm and worn smooth on inner edge (5.2.3 (e)) Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 2.5mm (5.2.3 (e)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9

MOT test number

Result

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7

MOT test number

836785279544

Result

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6

MOT test number

739458311395

Result

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #5 2016-06-27 09:33

MOT test number 243646696671

Result X Failed

Pass with rectification Nearside Front Headlamp aim too high (1.8)

Advice Rear fuel tank strap corroded

Fail Offside Rear coil spring broken (2.4.C.1a)

Pass with rectification Nearside Front Headlamp aim too high (1.8)

MOT #4 2015-06-29 10:33

MOT test number 579290185196

Result
✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2014-06-30 09:35

MOT test number 727141084181

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-06-25 16:45

MOT test number 205936173477

Result ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/13



Result

FV09RMO

report date: 2024-03-29

✓ Passed

 MOT #1
 2012-06-26 10:07

 MOT test number
 117048272156

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



X MOT

Tax expired:4 April 2023 **Expired:**30 May 2023

Tax status	Expired at 4 April 2023
Days left	391 days too late
MOT expiry date	30 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	biotom
UWNEI	nision
OWINCE	1113601

e when moterly	
For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report is	
STATE OF THE PARTY	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
	UK C
Planta since	
	More info >
	PIOLE IIIIO

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-01
Last registration	2022-05-31
Complete history	See info



Registration #1	2009-07-01	22 mi
Registration #2	2012-06-26	61.195 mi
Registration #3	2013-06-25	81.886 mi
Registration #4	2014-06-30	99.320 mi
Registration #5	2015-06-29	120.720 mi
Registration #6	2016-06-27	136.964 mi
Registration #7	2016-06-27	136.965 mi
Registration #8	2017-06-27	149.733 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		71,777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Max. allowed weight	2045 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

CAG172231