



report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA IG-T N-CONNECTA
Colour	White
Year of manufacture	2018
Top speed	109 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history


Entry 2

Date	2022-01-06
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

Entry 1

Date	2022-01-05
Pictures	37
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #4	2023-10-20 12:18
MOT test number	625752912551
Result	✓ Passed
Next expiry date	2024-10-22
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement STRONG ADVISE - front bush unbonded (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement STRONG ADVISE - front bush unbonded (5.3.4 (a) (i))

MOT #3	2023-10-19 10:21
MOT test number	419544740857
Result	✗ Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement STRONG ADVISE - front bush unbonded (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement STRONG ADVISE - front bush unbonded (5.3.4 (a) (i))



MOT #2	2022-10-10 09:59
MOT test number	275593155695
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking in treads (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking in treads (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #1	2021-10-22 08:12
MOT test number	123004685869
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking in treads (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking in treads (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-10-23
Last registration	2023-10-20
Complete history	See info



Registration #1	2018-10-23	7 mi
Registration #2	2021-10-22	35.926 mi
Registration #3	2023-10-20	35.926 mi
Registration #4	2023-10-20	35.926 mi
Registration #5	2023-10-20	35.926 mi
Registration #6	2023-10-20	35.926 mi
Registration #7	2023-10-20	35.926 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	79%
Pedestrian	79%
Safety systems	72%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1743 mm
Height	1455 mm
Length	3999 mm
Wheel base	2525 mm
Kerb weight	1068 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	272812