



AV60PUA

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 TREND H/R P/V
Colour	White
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	350 Nm at 2.400 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #11	2020-03-10 15:56
MOT test number	860826968461
Result	✓ Passed
Next expiry date	2021-03-09
Advice	Nearside Outer sill slight corrosion
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2019-02-20 14:32
MOT test number	294626393091
Result	✓ Passed

MOT #9	2018-03-09 09:12
MOT test number	273787364995
Result	✓ Passed
Advice	Offside Front Brake pipe slightly corroded x2 (3.6.B.2c)
Advice	Brake pedal rubber worn
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Rear Brake pipe slightly corroded and offside (3.6.B.2c)
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)

**MOT #8**

2018-02-24 11:21

MOT test number

193818391243

Result

✗ Failed

- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Central Brake pipe excessively corroded x4 (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement and offside (2.4.G.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Brake pipe slightly corroded x2 (3.6.B.2c)
- Advice** Brake pedal rubber worn
- Advice** Nearside Rear Brake pipe slightly corroded and offside (3.6.B.2c)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #7

2017-02-21 12:15

MOT test number

351830824361

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Central Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-02-20 09:45**MOT test number** 158856455782**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage insecure (2.4.G.1)**Fail** Offside Rear Leaf spring fractured (2.4.B.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Central Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Central Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-02-19 16:09**MOT test number** 822358367024**Result** ✓ Passed**MOT #4** 2016-02-17 16:32**MOT test number** 683919220914**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush broken (2.4.G.2)**Fail** Rear brake disc in such a condition that it is seriously weakened & pads (3.5.1i)**MOT #3** 2014-09-08 12:36**MOT test number** 968291854271**Result** ✓ Passed



MOT #2	2014-09-08 12:36
MOT test number	566181954210
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #1	2013-10-25 14:30
MOT test number	335218993414
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-10-31
Last registration	2020-03-10
Complete history	See info



Registration #1	2010-10-31	18 mi
Registration #2	2013-10-25	81.762 mi
Registration #3	2014-09-08	103.429 mi
Registration #4	2016-02-17	130.012 mi
Registration #5	2016-02-19	130.102 mi
Registration #6	2017-02-20	148.728 mi
Registration #7	2019-03-20	151.377 mi
Registration #8	2019-03-20	151.377 mi
Registration #9	2019-03-20	151.377 mi
Registration #10	2019-03-20	151.377 mi
Registration #11	2019-03-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2543 mm
Length	5680 mm
Kerb weight	1873 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AB29293