





report date: 2024-03-28

General information

Make	MINI
Model	COOPER AUTO COOPER
Colour	White
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-03-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-21
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #10	2024-02-19 14:14
MOT test number	366204896420
Result	✓ Passed
Next expiry date	2025-02-21
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #9	2023-02-20 10:33
MOT test number	655639676843
Result	✓ Passed
MOT #8	2022-02-22 10:56
MOT test number	229822730908
Result	✓ Passed

Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-01-29 11:51
MOT test number	105441888966
Result	✓ Passed
Advice Engine cover and under trays fitted	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2021-01-26 15:02

MOT test number 838432951034

Result X Failed

MAJOR Offside Front Headlamp aim not tested (4.1.2 (b))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Engine cover and under trays fitted..

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

MAJOR Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #5 2019-07-26 16:06

MOT test number 590606545792

Result ✓ Passed

MOT #4 2019-07-26 09:32

MOT test number 509785568751

Result × Failed

MAJOR Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)

(ii))

MOT #3 2018-06-28 11:38

MOT test number 686321620811

MOT #2 2017-08-29 11:20

MOT test number 602901704238

Result \rightarrow Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2016-09-13 14:36

MOT test number 484656956476

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union matery		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>		

	More info >	
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-27
Last registration	2024-02-19
Complete history	See info



Registration #1	2013-09-27	16 mi
Registration #2	2016-09-13	23.546 mi
Registration #3	2017-08-29	27.071 mi
Registration #4	2018-06-28	29.346 mi
Registration #5	2019-07-26	35.274 mi
Registration #6	2019-07-26	35.274 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number A638J527