



PJ59WBZ

report date: 2024-03-29

General information

Make	FIAT
Model	FIORINO 8V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-12
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	47
Total items failed	34

MOT #21	2024-03-25 10:54
MOT test number	136117173101
Result	✓ Passed
Next expiry date	2025-03-24
Advice	Rear Lower Gearbox mounting defective cracking
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2024-03-20 14:09

MOT test number

792042248657

Result**✗ Failed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Nearside Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail

Offside Front Tyre has ply or cords exposed outer edges (5.2.3 (d) (ii))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Offside Front Headlamp aim projected beam image is obviously incorrect head lamp foggy (4.1.2 (c))

Advice

Rear Lower Gearbox mounting defective cracking

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Nearside Front Tyre has ply or cords exposed inner edges (5.2.3 (d) (ii))

Fail

Nearside Front Headlamp aim projected beam image is obviously incorrect head lamp foggy (4.1.2 (c))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #19

2023-03-08 17:18

MOT test number

992638511156

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #18**

2023-03-07 18:30

MOT test number

598921115902

Result**✗ Failed**

- Fail** Oil leaking excessively from engine oil filter housing (8.4.1 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Front Suspension arm insecurely attached (5.3.3 (a) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases flexi pipe damaged (6.1.2 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #17

2022-01-17 12:09

MOT test number

949691686550

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement both front noisy (5.3.4 (a) (i))

**MOT #16**

2022-01-14 15:50

MOT test number

914997522457

Result**✗ Failed**

- Fail** Position lamp switch does not operate in accordance with the requirements (4.2.2 (a))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Tyre has ply or cords exposed both front (5.2.3 (d) (ii))
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement both front noisy (5.3.4 (a) (i))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #15

2021-02-10 13:38

MOT test number

937392280700

Result**✓ Passed**

- Advice** Washer bottle leaking
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside front tyre worn on inside edge
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #14**

2021-02-10 12:49

MOT test number

824450661981

Result**✗ Failed****Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Offside front tyre worn on inside edge

Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Washer bottle leaking

MOT #13

2020-01-08 10:38

MOT test number

145576419505

Result**✓ Passed****Advice**

Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2019-03-04 13:00

MOT test number

152740058756

Result**✓ Passed****Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2019-03-01 15:52**MOT test number** 453748824238**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Side repeater likely to become detached both (4.4.1 (c) (ii))**MOT #10** 2018-04-28 09:52**MOT test number** 498886006957**Result** ✓ Passed**MOT #9** 2018-04-28 09:52**MOT test number** 241553685759**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #8** 2017-05-24 12:07**MOT test number** 532841150551**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-05-17 10:13**MOT test number** 192489108967**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.B.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #6** 2016-03-22 16:31**MOT test number** 953878407791**Result** ✓ Passed**Advice** Nearside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**MOT #5** 2016-03-22 11:21**MOT test number** 960980577047**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #4	2015-04-09 15:04
MOT test number	195229595034
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2014-03-24 18:22
MOT test number	935683084075
Result	✓ Passed

MOT #2	2012-12-11 16:39
MOT test number	649366042329
Result	✓ Passed

MOT #1	2012-12-11 15:50
MOT test number	475066242349
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.D.2c)



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2024

✓
MOT

Expires:
24 March 2025

Tax status

Expired at 1 April 2024

Days left

28 days too late

MOT expiry date

24 March 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-12-17
Last registration	2024-03-25
Complete history	See info



Registration #1	2009-12-17	14 mi
Registration #2	2012-12-11	28.601 mi
Registration #3	2012-12-11	28.602 mi
Registration #4	2014-03-24	37.534 mi
Registration #5	2015-04-09	43.971 mi
Registration #6	2016-03-22	49.130 mi
Registration #7	2016-03-22	49.130 mi
Registration #8	2017-05-17	59.936 mi
Registration #9	2017-05-24	59.936 mi
Registration #10	2018-04-28	64.328 mi
Registration #11	2018-04-28	64.328 mi
Registration #12	2019-03-01	64.417 mi
Registration #13	2019-03-01	64.417 mi
Registration #14	2019-03-01	64.417 mi
Registration #15	2019-03-01	64.417 mi
Registration #16	2019-03-01	64.417 mi
Registration #17	2019-03-01	64.417 mi
Registration #18	2019-03-01	64.417 mi
Registration #19	2019-03-01	64.417 mi
Registration #20	2019-03-01	64.417 mi
Registration #21	2019-03-01	64.417 mi
Registration #22	2019-03-01	64.417 mi
Registration #23	2019-03-01	64.417 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Engine number	5929618