



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION
Colour	Grey
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





## MOT history

MOT expiry date	2021-09-28
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	8
Total items failed	5

MOT #14	2020-09-29 15:44
MOT test number	793683232560
Result	✓ Passed
Next expiry date	2021-09-28

MOT #13	2020-09-29 15:44
MOT test number	168833763050
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #12	2019-09-26 13:06
MOT test number	102052545112
Result	✓ Passed

MOT #11	2019-09-26 13:06
MOT test number	685628108242
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #10	2018-09-13 11:37
MOT test number	658279093647
Result	✓ Passed

**MOT #9** 2017-09-25 12:50**MOT test number** 787153935365**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-09-24 09:00**MOT test number** 664750539924**Result** ✓ Passed**MOT #7** 2015-09-25 12:13**MOT test number** 748436136930**Result** ✓ Passed**MOT #6** 2014-09-06 09:34**MOT test number** 379649144418**Result** ✓ Passed**MOT #5** 2014-09-05 16:04**MOT test number** 399108644275**Result** ✓ Passed**MOT #4** 2014-08-22 14:53**MOT test number** 146764834225**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)

**MOT #3** 2013-09-02 15:13**MOT test number** 908075043206**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-09-02 09:56**MOT test number** 765985243281**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2012-09-07 15:04**MOT test number** 867451852257**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Under-trays fitted obscuring some underside components**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LD59GDU</b>
Plate since	2019-06-29
Current registration	 <b>LD59GDU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-22
Last registration	2020-09-29
Complete history	<a href="#">See info</a>



Registration #1	2009-09-22	14 mi
Registration #2	2012-09-07	92.733 mi
Registration #3	2013-09-02	121.585 mi
Registration #4	2013-09-02	121.585 mi
Registration #5	2014-08-22	145.003 mi
Registration #6	2014-09-05	145.003 mi
Registration #7	2014-09-06	145.003 mi
Registration #8	2015-09-25	101.055 mi
Registration #9	2016-09-29	101.055 mi
Registration #10	2017-09-29	101.055 mi
Registration #11	2018-09-29	101.055 mi
Registration #12	2019-09-29	101.055 mi
Registration #13	2020-09-29	101.055 mi
Registration #14	2021-09-29	101.055 mi
Registration #15	2022-09-29	101.055 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1840 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAY 152257