



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Silver
Year of manufacture	2007
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K







Internet history

Entry 1

Date	2022-02-28
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-13
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	24
Total items failed	25

MOT #21	2022-07-06 08:22
MOT test number	683764717689
Result	✓ Passed
Next expiry date	2023-07-13
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

MOT #20	2022-07-02 11:03
MOT test number	217088717944
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Fail	Service brake excessively binding Both rear (park brake sticking) (1.2.1 (f))



MOT #19	2021-07-14 16:26
MOT test number	680994911205
Result	✓ Passed
Advice	Vehicle under-body has signs of corrosion
Advice	Tyre worn close to legal limit/worn on edge ALL + CRACKED (5.2.3 (e))

MOT #18	2021-07-14 08:55
MOT test number	671791187935
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Vehicle under-body has signs of corrosion
Advice	Tyre worn close to legal limit/worn on edge ALL + CRACKED (5.2.3 (e))
Fail	Front Headlamp aim projected beam image is obviously incorrect ***BOTH SIDES*** (4.1.2 (c))

MOT #17	2020-07-14 08:27
MOT test number	769031499693
Result	✓ Passed

MOT #16	2020-07-07 13:46
MOT test number	653821025668
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #15** 2019-06-08 10:04**MOT test number** 663764411408**Result** ✓ Passed**MOT #14** 2019-06-08 10:04**MOT test number** 963933378375**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #13** 2018-06-13 13:31**MOT test number** 268083272503**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Exhaust bracket broken at rear , but exhaust unlikely to fall off**Advice** Offside Front brake pipe corroded**MOT #12** 2018-06-13 09:28**MOT test number** 119934314913**Result** ✗ Failed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened side (1.1.14 (a) (ii))**Advice** Exhaust bracket broken at rear , but exhaust unlikely to fall off**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened side (1.1.14 (a) (ii))**Advice** Offside Front brake pipe corroded**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11**

2017-06-12 14:08

MOT test number

523805691630

Result

✓ Passed

Advice Wear & deterioration in front brake discs**Advice** Offside Rear Brake pipe slightly corroded to hose (3.6.B.2c)**MOT #10**

2017-06-10 09:37

MOT test number

901583676986

Result

✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Rear Brake pipe slightly corroded to hose (3.6.B.2c)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint rear arm (2.5.B.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Wear & deterioration in front brake discs**MOT #9**

2016-06-13 10:37

MOT test number

476193786173

Result

✓ Passed

MOT #8

2015-07-28 12:09

MOT test number

169169205201

Result

✓ Passed

Notice Advise centre exhaust bracket corroded**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #7** 2015-07-28 08:44**MOT test number** 229429305299**Result** ✗ Failed**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Advise centre exhaust bracket corroded**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #6** 2014-06-27 08:58**MOT test number** 785298074125**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #5** 2013-07-19 09:05**MOT test number** 525530003210**Result** ✓ Passed**MOT #4** 2013-07-18 15:24**MOT test number** 155859093175**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Rear Upper Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #3** 2012-07-18 13:58**MOT test number** 455370602295**Result** ✓ Passed



MOT #2	2011-07-22 15:55
MOT test number	189993001211
Result	✓ Passed
MOT #1	2010-07-16 11:28
MOT test number	264017990190
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	YS07XKO
Plate since	2019-06-29
Current registration	YS07XKO
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-07-26
Last registration	2022-07-06
Complete history	See info



Registration #1	2007-07-26	28 mi
Registration #2	2010-07-16	19.058 mi
Registration #3	2011-07-22	26.844 mi
Registration #4	2012-07-18	32.178 mi
Registration #5	2013-07-18	47.292 mi
Registration #6	2013-07-19	47.292 mi
Registration #7	2014-06-27	61.338 mi
Registration #8	2015-07-28	73.108 mi
Registration #9	2015-07-28	73.108 mi
Registration #10	2016-06-13	86.964 mi
Registration #11	2017-06-10	91.081 mi
Registration #12	2017-06-12	91.107 mi
Registration #13	2018-06-13	91.107 mi
Registration #14	2018-06-13	91.107 mi
Registration #15	2018-06-13	91.107 mi
Registration #16	2018-06-13	91.107 mi
Registration #17	2018-06-13	91.107 mi
Registration #18	2018-06-13	91.107 mi
Registration #19	2018-06-13	91.107 mi
Registration #20	2018-06-13	91.107 mi
Registration #21	2018-06-13	91.107 mi
Registration #22	2018-06-13	91.107 mi
Registration #23	2018-06-13	91.107 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530941442