





General information

Make	NISSAN
Model	350 Z V6 GT
Colour	Black
Year of manufacture	2007
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	308 BHP	0 < 101 A
Max. torque	358 Nm at 4.800 rpm	101 - 120 ^B _C
Engine capacity	3.498 cc	121 - 140 P
Cylinders	6	141 - 165 ^F _G
Fuel type	Petrol	166 - 185 H
Consumption city	16.8 mpg	186 - 225 J
Consumption extra urban	32.1 mpg	225+ L L
Consumption combined	24.1 mpg	
CO2 emission	280 g/km	
CO2 label	М	

м





Internet history

Entry	1

Date Pictures 2021-08-01

15

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	15
Total items failed	10

MOT #16		2023-10-31 11:31
MOT test	number	940138662885
Result		Passed
Next expi	ry date	2024-10-31
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))





MOT #15	2023-10-26 11:04
MOT test number	193540159685
Result	🗙 Failed
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #14	2022-11-01 14:35
MOT test number	699320143904
Result	✓ Passed

MOT #3	13	2022-10-31 12:58
MOT te	st number	606213108308
Result		🗙 Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Rear fog lamp not working (4.5.1 (a) (ii))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail	Emissions not tested (8.2.1.2 (d))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	





MOT #12	2021-07-05 15:03
MOT test number	654914555259
Result	✓ Passed
MOT #11	2020-03-20 12:25
MOT test number	333681320687
Result	✓ Passed
MOT #10	2019-04-18 15:16
MOT test number	973678664873
Result	✓ Passed
MOT #9	2018-04-20 13:27
MOT test number	772671774936
Result	✓ Passed
MOT #8 MOT test number	2017-04-07 10:09
	751474196196
Result	✓ Passed
MOT #7	2015-11-30 10:54
MOT test number	281640168835
Result	✓ Passed
Advice Mil light on	
МОТ #6	2014-11-21 09:22
MOT test number	407775224486
Result	✓ Passed

Notice

Under-trays fitted obscuring some underside components



MOT #5		2013-10-03 09:45
MOT test	number	347506273287
Result		✓ Passed
Notice	Both outer sills and under wheel arches covered	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Engine covers fitted obscuring some components in the engine bay	

МОТ #4	2012-09-19 17:20
MOT test number	825843562265
Result	✓ Passed
Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	

MOT #3	2012-02-17 08:48
MOT test number	137668942493
Result	✓ Passed
MOT #2	2011-02-17 16:56
MOT test number	979528741088
Result	✓ Passed
MOT #1	2010-11-02 11:09
MOT test number	602846400307

Result

🗸 Passed

HJ57WVA report date: 2024-03-29



Tax & MOT check

✓ Taxed	√ MOT
Tax due: 1 November 2024	Expires: 31 October 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-23
Last registration	2023-10-31
Complete history	See info



Registration #1	2007-11-23	12 mi
Registration #2	2010-11-02	20.609 mi
Registration #3	2011-02-17	21.619 mi
Registration #4	2012-02-17	26.033 mi
Registration #5	2012-09-19	28.675 mi
Registration #6	2013-10-03	36.322 mi
Registration #7	2014-11-21	41.454 mi
Registration #8	2015-11-30	49.961 mi
Registration #9	2017-04-07	58.918 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.117 esi

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Dimensions & weight

Width	1815 mm
Height	1325 mm
Length	4315 mm
Wheel base	2650 mm
Kerb weight	1542 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	589046