





report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX LX TDCI
Colour	Blue
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-07

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-02-23
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	17
Total items failed	10

MOT #	21	2024-02-27 14:11
MOT te	est number	511201307365
Result		× Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail	Nearside Front Anti-roll bar ball joint dust cover missing (5.3.4 (b) (ii))	
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c	:))
Fail ingress	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no long of dirt $(6.1.7 (g) (ii))$	ger prevents the
Fail	Front Exhaust has a major leak of exhaust gases exhaust flexy (6.1.2 (a))	

MOT #20	2023-02-15 12:01
MOT test number	372044668471
Result	✓ Passed

MOT #	19	2023-02-13 09:05
MOT te	est number	787564764277
Result		X Failed
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #18 2022-02-21 12:37 **MOT** test number 326369387227 ✓ Passed Result **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii)) **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) Advice Front Headlamps have mist (both) Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17

MOT test number

363406256652

Result

✓ Passed

MOT #16

2020-01-29 11:54

MOT test number 334064358800

Result ✓ Passed

 MOT #15
 2019-01-25 10:31

 MOT test number
 717380579773

 Result
 ✓ Passed

MOT #14 2018-01-30 12:12

MOT test number 487307751307

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 4/14



report date: 2024-03-28

× Failed

MOT #13 2018-01-30 12:12

MOT test number 840465791259

Result X Failed

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #12 2017-01-11 10:03

MOT test number 204081277326

Advice Vehicle underbody and suspension components slightly corroded

Advice Offside Rear tyre perished

Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)

MOT #11 2016-01-19 13:51

MOT test number 729148975017

Result \rightarrow Passed

Advice N/s rear tyre slightly perished

MOT #10 2016-01-19 10:18

MOT test number 587743370611

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice N/s rear tyre slightly perished

Result

MOT #9 2015-01-15 09:53

MOT test number 929815015026

Result

Passed

CarCheck.co.uk page 5/14



MOT #3

MOT test number

CV54DDL

report date: 2024-03-28

2009-01-23 12:01

144929238044

MOT #8	2014-01-21 10:52
MOT test number	489021624039
Result	✓ Passed
MOT #7	2013-01-17 12:39
MOT test number	129657113083
Result	✓ Passed
MOT #6	2012-02-06 10:24
MOT test number	726057032091
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #5	2011-01-27 12:09
MOT test number	125307421441
Result	✓ Passed
MOT #4	2010-01-28 14:52

MOT test number	703898920015
Result	✓ Passed
Notice N/s/f tyre worn on edges	

MOT test number	133943529036
Result	√ Passed
MOT #2	2008-02-08 16:09

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 6/14



MOT #1 2007-10-11 11:30

MOT test number 990664487249

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	23 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes See in this check if this FORD had different number plates.	
Number of plates	,
Correct registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-11-13
Last registration	2024-02-27
Complete history	See info



Registration #1	2004-11-13	14 mi
Registration #2	2007-10-11	12.857 mi
Registration #3	2008-02-08	13.871 mi
Registration #4	2009-01-23	15.963 mi
Registration #5	2010-01-28	17.591 mi
Registration #6	2011-01-27	18.935 mi
Registration #7	2012-02-06	19.952 mi
Registration #8	2013-01-17	22.984 mi
Registration #9	2014-01-21	24.078 mi
Registration #10	2015-01-15	25.193 mi
Registration #11	2016-01-19	25.803 mi
Registration #12	2016-01-19	25.803 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Danistration #22		
Registration #22		n

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1392 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	4/14

Number of axles 2

Engine number 3M40629