



Mercedes-Benz



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | MERCEDES |
| Model | CLK CLK200K AVANTGARDE |
| Colour | Black |
| Year of manufacture | 2005 |
| Top speed | 142 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 240 Nm at 4.000 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 22.4 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 32.5 mpg |
| CO2 emission | 207 g/km |
| CO2 label | K |






Internet history

Entry 2



| | |
|---------------|-----------------------------|
| Date | 2021-09-11 |
| Pictures | 38 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-10 |
| Pictures | 38 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-26 |
| MOT pass rate | 76 % |
| MOT passed | 16 |
| Failed MOT tests | 5 |
| Total advice items | 35 |
| Total items failed | 10 |

| | |
|------------------|---|
| MOT #21 | 2023-10-02 09:06 |
| MOT test number | 492055653784 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-26 |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #20 | 2022-10-27 13:12 |
| MOT test number | 186641167150 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

**MOT #19** 2022-10-14 13:55**MOT test number** 658191109770**Result** ✗ Failed**Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18** 2021-09-30 08:12**MOT test number** 757926793135**Result** ✓ Passed**MOT #17** 2021-09-28 08:05**MOT test number** 595455494613**Result** ✗ Failed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #16** 2020-10-23 16:17**MOT test number** 886268093602**Result** ✓ Passed

**MOT #15**

2020-10-19 16:00

MOT test number

611625325458

Result

✗ Failed

Fail

Suspension arm ball joint excessively worn O/S/F lower rear (5.3.4 (a) (i))

Fail

Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Suspension arm ball joint excessively worn N/S/F lower rear (5.3.4 (a) (i))

Fail

Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14

2019-09-26 10:23

MOT test number

664295747934

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Items removed from driver's view prior to test

MOT #13

2018-09-12 15:01

MOT test number

238732165089

Result

✓ Passed

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))

Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12**

2018-09-07 08:13

MOT test number

150522747395

Result**✗ Failed****Advice**

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))

Fail

Offside Front Coil spring fractured or broken broken (5.3.1 (b) (i))

Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))

MOT #11

2017-08-29 11:17

MOT test number

512208768166

Result**✓ Passed****MOT #10**

2016-09-15 08:28

MOT test number

770460465108

Result**✓ Passed****Advice**

Offside Front Suspension arm has slight play in a ball joint rear arm (2.4.G.2)

MOT #9

2016-09-07 14:42

MOT test number

390446180986

Result**✗ Failed****Fail**

Nearside Front Suspension arm has excessive play in a ball joint rear arm (2.4.G.2)

Advice

Offside Front Suspension arm has slight play in a ball joint rear arm (2.4.G.2)

**MOT #8** 2015-08-28 11:41**MOT test number** 558860845283**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Nail in nearside rear tyre
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #7 2014-09-10 10:10**MOT test number** 167993254231**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2013-09-09 11:36**MOT test number** 696072653244**Result** ✓ Passed**MOT #5** 2012-09-05 17:14**MOT test number** 637619542276**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #4 | 2011-09-24 11:04 |
| MOT test number | 396027761432 |
| Result | ✓ Passed |
| MOT #3 | 2010-09-10 12:46 |
| MOT test number | 331083250418 |
| Result | ✓ Passed |
| MOT #2 | 2009-09-25 10:47 |
| MOT test number | 741508369207 |
| Result | ✓ Passed |
| MOT #1 | 2008-09-12 12:16 |
| MOT test number | 432376758229 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 26 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXX |
| Plate since | 2024-03-29 |
| Current registration |  XXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2005-09-27 |
| Last registration | 2023-10-02 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2005-09-27 | 18 mi |
| Registration #2 | 2008-09-12 | 28.750 mi |
| Registration #3 | 2009-09-25 | 36.909 mi |
| Registration #4 | 2010-09-10 | 43.768 mi |
| Registration #5 | 2011-09-24 | 51.283 mi |
| Registration #6 | 2012-09-05 | 58.141 mi |
| Registration #7 | 2013-09-09 | 65.508 mi |
| Registration #8 | 2014-09-10 | 71.663 mi |
| Registration #9 | 2015-08-28 | 76.499 mi |
| Registration #10 | 2016-09-07 | 82.047 mi |
| Registration #11 | 2016-09-15 | 82.169 mi |
| Registration #12 | 2017-08-29 | 88.643 mi |
| Registration #13 | 2018-08-29 | 95.117 mi |
| Registration #14 | 2019-08-29 | 101.591 mi |
| Registration #15 | 2020-08-29 | 108.065 mi |
| Registration #16 | 2021-08-29 | 114.539 mi |
| Registration #17 | 2022-08-29 | 121.013 mi |
| Registration #18 | 2023-08-29 | 127.487 mi |
| Registration #19 | 2023-08-29 | 133.961 mi |
| Registration #20 | 2023-08-29 | 140.435 mi |
| Registration #21 | 2023-08-29 | 146.909 mi |
| Registration #22 | 2023-08-29 | 153.383 mi |
| Registration #23 | 2023-08-29 | 159.857 mi |
| Registration #24 | 2023-08-29 | 166.331 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1415 mm |
| Length | 4652 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1615 kg |
| Max. allowed weight | 2010 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 27194030678660 |