



General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Black
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-29
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #11 2023-07-21 16:31

MOT test number 660111420753

Result ✓ Passed

Next expiry date 2024-07-24

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm rear bush (5.3.4 (a) (i))

MOT #10 2023-07-21 13:23

MOT test number 500800183067

Result ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure nail in inner tyre which has caused a lump in tyre wall (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm rear bush (5.3.4 (a) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Headlamps matched pair are not the same colour headlight showing blue light (4.1.4 (d))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Suspension arm pin or bush excessively worn bottom arm rear bush (5.3.4 (a) (i))

**MOT #9** 2022-07-20 12:17**MOT test number** 887628968145**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both Osf and Nsf (5.3.4 (a) (i))**MOT #8** 2021-07-23 12:42**MOT test number** 723761062013**Result** ✓ Passed**MOT #7** 2021-07-22 13:47**MOT test number** 362622124691**Result** ✗ Failed**Fail** Windscreen washer not working leaking from bottal (3.5 (a))**Fail** Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both sides (5.2.3 (d) (i))**MOT #6** 2020-07-25 14:18**MOT test number** 533371395382**Result** ✓ Passed**Advice** Insufficient diesel smoke emissions to trigger test equipment**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Engine cover and undertray fitted obscuring some components**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5** 2020-07-25 08:15**MOT test number** 417629897944**Result** ✗ Failed

- Advice** Insufficient diesel smoke emissions to trigger test equipment
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Advice** Engine cover and undertray fitted obscuring some components
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2019-05-08 10:18**MOT test number** 230063010991**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
- Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

MOT #3 2018-04-10 08:35**MOT test number** 932943099879**Result** ✓ Passed

- Advice** Engine cover fitted
- Advice** Oil leak
- Advice** Undertray fitted

MOT #2 2017-09-07 13:47**MOT test number** 303992034207**Result** ✓ Passed



MOT #1	2017-05-16 15:27
MOT test number	568061701059
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RO14VUV
Plate since	2024-03-29
Current registration	 RO14VUV
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-17
Last registration	2023-07-21
Complete history	See info



Registration #1	2014-07-17	8 mi
Registration #2	2017-05-16	26.235 mi
Registration #3	2017-09-07	28.014 mi
Registration #4	2018-04-10	37.565 mi
Registration #5	2019-05-08	48.114 mi
Registration #6	2020-07-25	58.017 mi
Registration #7	2020-07-25	58.017 mi
Registration #8	2020-07-25	58.017 mi
Registration #9	2020-07-25	58.017 mi
Registration #10	2020-07-25	58.017 mi
Registration #11	2020-07-25	58.017 mi
Registration #12	2020-07-25	58.017 mi
Registration #13	2020-07-25	58.017 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBK81075