



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2006
Top speed	143 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-12
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-18
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #18	2024-03-19 12:42
MOT test number	143223284658
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both front (4.1.4 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17	2024-03-18 14:33
MOT test number	804234609222
Result	✗ Failed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Fail	Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength rear axel excessively corroded (5.3.6 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both front (4.1.4 (b))

**MOT #16** 2023-07-14 14:46**MOT test number** 587428417903**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2022-07-07 14:30**MOT test number** 306589702987**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2021-07-31 08:41**MOT test number** 619022929376**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material all rear pipes (1.1.11 (c))**MOT #13** 2019-06-07 13:28**MOT test number** 976497696315**Result** ✓ Passed**MOT #12** 2019-06-03 11:42**MOT test number** 599209207342**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Both rear tyre rotation the wrong way round**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #11** 2018-01-05 12:33**MOT test number** 988541579358**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #10** 2016-12-05 14:00**MOT test number** 339851507324**Result** ✓ Passed**MOT #9** 2015-12-01 13:20**MOT test number** 899395410518**Result** ✓ Passed**MOT #8** 2015-12-01 13:20**MOT test number** 638303706316**Result** ✗ Failed**Pass with rectification** Headlamp aim too high (1.8)**MOT #7** 2014-11-18 09:15**MOT test number** 879922424306**Result** ✓ Passed**MOT #6** 2013-11-26 17:07**MOT test number** 195370933336**Result** ✓ Passed

**MOT #5** 2013-11-26 14:22**MOT test number** 588780433372**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2012-11-30 12:01**MOT test number** 468625732324**Result** ✓ Passed**MOT #3** 2011-11-26 09:49**MOT test number** 436710731444**Result** ✓ Passed**MOT #2** 2010-11-24 09:33**MOT test number** 412888520374**Result** ✓ Passed**MOT #1** 2009-11-10 11:27**MOT test number** 852444319343**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
19 February 2024

✓

MOT

Expires:
18 March 2025

Tax status	Expired at 19 February 2024
Days left	70 days too late
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 EJ56VHK
Plate since	2019-06-29
Current registration	 EJ56VHK
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-11-10
Last registration	2024-03-19
Complete history	See info



Registration #1	2006-11-10	14 mi
Registration #2	2009-11-10	25.208 mi
Registration #3	2010-11-24	53.835 mi
Registration #4	2011-11-26	58.028 mi
Registration #5	2012-11-30	60.430 mi
Registration #6	2013-11-26	64.470 mi
Registration #7	2013-11-26	64.470 mi
Registration #8	2014-11-18	67.903 mi
Registration #9	2015-12-01	72.878 mi
Registration #10	2015-12-01	72.878 mi
Registration #11	2016-03-20	75.377 mi
Registration #12	2016-03-20	75.377 mi
Registration #13	2016-03-20	75.377 mi
Registration #14	2016-03-20	75.377 mi
Registration #15	2016-03-20	75.377 mi
Registration #16	2016-03-20	75.377 mi
Registration #17	2016-03-20	75.377 mi
Registration #18	2016-03-20	75.377 mi
Registration #19	2016-03-20	75.377 mi
Registration #20	2016-03-20	75.377 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430771231