



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE S
Colour	Black
Year of manufacture	2005
Top speed	102 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-06
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-01-17
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	20
Total items failed	13

MOT #20	2021-01-18 16:25
MOT test number	232574585427
Result	✓ Passed
Next expiry date	2022-01-17
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #19	2021-01-18 16:25
MOT test number	261518408957
Result	✗ Failed
Pass with rectification	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #18	2019-07-18 10:43
MOT test number	634573573023
Result	✓ Passed

MOT #17	2019-07-18 10:43
MOT test number	720949320819
Result	✗ Failed
Pass with rectification	Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #16** 2018-12-13 16:52**MOT test number** 225249908872**Result** ✓ Passed**MOT #15** 2018-06-21 11:38**MOT test number** 858542082260**Result** ✓ Passed**MOT #14** 2017-06-22 09:17**MOT test number** 389712089788**Result** ✓ Passed**MOT #13** 2017-06-22 09:17**MOT test number** 552778608583**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator not working (1.4.A.2c)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #12** 2016-06-08 09:30**MOT test number** 421489992947**Result** ✓ Passed**MOT #11** 2015-06-19 10:38**MOT test number** 499690675182**Result** ✓ Passed

**MOT #10** 2014-06-23 09:14**MOT test number** 208424774444**Result** ✓ Passed**Notice** ADVISE damage to nearside front outer sill**MOT #9** 2013-06-19 14:57**MOT test number** 868150773159**Result** ✓ Passed**MOT #8** 2013-06-19 09:33**MOT test number** 425720073134**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2012-06-22 15:00**MOT test number** 937094072100**Result** ✓ Passed**Notice** ADVISE cracking on inner shoulder of the offside rear tyre also slightly out of shape**Advice** Nearside Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)**Notice** Play in steering rack inner joint(s)

**MOT #6** 2012-06-22 10:00**MOT test number** 606964172171**Result** ✗ Failed

- Notice** ADVISE both offside front and rear tyres have nails in them and ARE PUNCTURED
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)
- Notice** Play in steering rack inner joint(s)
- Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #5 2011-06-16 11:26**MOT test number** 228067661114**Result** ✓ Passed

- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Notice** ADVISE minor damage to nearside outer sill
- Notice** Trim on drivers seat split and scratches on bodywork

MOT #4 2010-06-17 13:57**MOT test number** 860428160182**Result** ✓ Passed

- Notice** ADVISE staining on fuel filter NO LEAK AT TIME OF TEST advise replacement
- Notice** Noise on gearbox when wheels rotated.
- Notice** Scratch on offside door rear arch bumper and nearside outer sill damaged.

**MOT #3** 2010-06-17 09:26**MOT test number** 153178660108**Result** ✗ Failed**Notice** Noise on gearbox when wheels rotated.**Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)**Notice** Scratch on offside door rear arch bumper and nearside outer sill damaged.**Fail** Centre Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** ADVISE staining on fuel filter NO LEAK AT TIME OF TEST advise replacement**MOT #2** 2009-06-15 12:05**MOT test number** 652226069141**Result** ✓ Passed**Notice** Nearside/offside front tyres fitted are mud/snow. also nearside rear**MOT #1** 2008-06-16 12:48**MOT test number** 223958168138**Result** ✓ Passed



Tax & MOT check

<div><div>X</div><div>Untaxed</div><div>Tax expired: 22 September 2021</div></div>		<div><div>X</div><div>MOT</div><div>Expired: 17 January 2022</div></div>	
Tax status		Expired at 22 September	
Days left		950 days too late	
MOT expiry date		17 January 2022	
Full MOT history		See MOT history	

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 XXXXXX
Plate since	2019-06-29
Current registration	 XXXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-06-24
Last registration	2021-01-18
Complete history	See info



Registration #1	2005-06-24	27 mi
Registration #2	2008-06-16	33.718 mi
Registration #3	2009-06-15	42.232 mi
Registration #4	2010-06-17	51.270 mi
Registration #5	2010-06-17	51.270 mi
Registration #6	2011-06-16	61.205 mi
Registration #7	2012-06-22	71.893 mi
Registration #8	2012-06-22	71.893 mi
Registration #9	2013-06-19	81.450 mi
Registration #10	2013-06-19	84.450 mi
Registration #11	2014-06-23	89.512 mi
Registration #12	2015-06-23	95.577 mi
Registration #13	2016-06-23	101.642 mi
Registration #14	2017-06-23	107.707 mi
Registration #15	2018-06-23	113.772 mi
Registration #16	2019-06-23	119.837 mi
Registration #17	2020-06-23	125.902 mi
Registration #18	2021-01-18	131.967 mi
Registration #19	2021-01-18	131.967 mi
Registration #20	2021-01-18	131.967 mi
Registration #21	2021-01-18	131.967 mi
Registration #22	2021-01-18	131.967 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1485 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1319 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BCA423376