



report date: 2024-03-29

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-19
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #19</b>	2021-03-11 17:19
<b>MOT test number</b>	268652976294
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-03-11
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #18</b>	2021-03-11 10:25
<b>MOT test number</b>	691563432326
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Fail</b>	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
<b>Fail</b>	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Fail</b>	Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
<b>Fail</b>	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

<b>MOT #17</b>	2020-03-02 17:03
<b>MOT test number</b>	428702431241
<b>Result</b>	✓ Passed

**MOT #16** 2020-03-02 14:01**MOT test number** 689507312272**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15** 2019-02-25 09:27**MOT test number** 965299438814**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2018-03-12 15:16**MOT test number** 341856367386**Result** ✓ Passed**MOT #13** 2018-02-22 19:38**MOT test number** 806764655494**Result** ✗ Failed

- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #12**

2017-03-02 11:42

**MOT test number**

475574370877

**Result**

✓ Passed

- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Front coil spring corroded ns/os (2.4.C.1b)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Front Wishbone Bush (2.4.G.2)
- Advice** Rear coil spring corroded ns/os (2.4.C.1b)
- Advice** Front Shock absorber has slight corrosion to the casing ns/os (2.7.2a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Front Wishbone Bush (2.4.G.2)

**MOT #11**

2016-02-16 10:47

**MOT test number**

993020173512

**Result**

✓ Passed

**MOT #10**

2015-02-13 11:57

**MOT test number**

735074945066

**Result**

✓ Passed

- Notice** Both front tyres worn close to legal limit.
- Notice** Front & rear brake discs & pads wearing thin.
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #9** 2015-02-13 11:57**MOT test number** 348104045054**Result** ✗ Failed**Notice** Both front tyres worn close to legal limit.**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Front & rear brake discs & pads wearing thin.**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-02-13 15:10**MOT test number** 765544244045**Result** ✓ Passed**Notice** Front brake discs & pads wearing thin.**MOT #7** 2014-02-13 12:27**MOT test number** 696104744030**Result** ✗ Failed**Notice** Front brake discs & pads wearing thin.**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #6** 2013-02-14 16:58**MOT test number** 165095043065**Result** ✓ Passed

**MOT #5** 2013-02-14 11:24**MOT test number** 109425643471**Result** ✗ Failed

- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #4** 2012-02-23 10:11**MOT test number** 755474652014**Result** ✓ Passed**MOT #3** 2011-05-18 14:47**MOT test number** 348778831199**Result** ✓ Passed**MOT #2** 2010-05-19 16:04**MOT test number** 654649530163**Result** ✓ Passed

- Notice** Nearside front brake has a slight bind
- Notice** Child seat fitted not allowing full inspection of adult belt



MOT #12010-05-19 14:51

MOT test number931299830176

Result

Failed

Notice

Nearside front brake has a slight bind

Fail

Parking brake lever has no reserve travel (3.1.6b)

Fail

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice

Child seat fitted not allowing full inspection of adult belt

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LD07NXC
Plate since	2024-03-29
Current registration	LD07NXC
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-19
Last registration	2021-03-11
Complete history	<a href="#">See info</a>



Registration #1	2007-05-19	22 mi
Registration #2	2010-05-19	16.226 mi
Registration #3	2010-05-19	16.226 mi
Registration #4	2011-05-18	20.970 mi
Registration #5	2012-02-23	23.028 mi
Registration #6	2013-02-14	33.987 mi
Registration #7	2013-02-14	33.987 mi
Registration #8	2014-02-13	44.068 mi
Registration #9	2014-02-13	44.068 mi
Registration #10	2015-02-13	52.837 mi
Registration #11	2015-05-20	55.557 mi
Registration #12	2015-05-20	55.557 mi
Registration #13	2015-05-20	55.557 mi
Registration #14	2015-05-20	55.557 mi
Registration #15	2015-05-20	55.557 mi
Registration #16	2015-05-20	55.557 mi
Registration #17	2015-05-20	55.557 mi
Registration #18	2015-05-20	55.557 mi
Registration #19	2015-05-20	55.557 mi
Registration #20	2015-05-20	55.557 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1657 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Engine number**

D4EA6H24117