





report date: 2024-03-29

### General information

Make	FORD
Model	GALAXY LX TDCI
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-11-16

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

#### **MOT** history

MOT #17

MOT test number

860906628087

Result

Next expiry date

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT test number

129497914477

Result

Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #15	2020-11-06 14:31
MOT test number	368627759274
Result	✓ Passed

MO1 #14	2019-05-10 08:47
MOT test number	527368309449
Result	✓ Passed

MOT #13	2019-05-04 11:03
MOT test number	463264234750
Result	<b>×</b> Failed
Fail Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)	))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #12		2017-12-08 14:17
MOT test	number	419438486926
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #11		2016-11-08 12:06
MOT test	number	356463933987
Result		✓ Passed
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened and front	(3.5.1i)
Advice	Central Rear Outer Child Seat fitted not allowing full inspection of adult belt	

MOT #10	2016-01-19 14:33
MOT test number	547076575585
Result	✓ Passed
MOT #9	2014-09-22 11:46
MOT test number	608435364267
Result	✓ Passed
MOT #8	2013-09-30 11:58
MOT test number	418163673223
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Offside Side repeater not working (1.4.A.2c)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification

Nearside Headlamp aim too high (1.8)

MOT #6

MOT test number

Result

Notice Airbag warning light on

MOT #5

MOT test number

699660372251

Result

Pass with rectification
Upper Stop lamp not working (1.2.1b)

Notice Airbag warning light on

2011-09-28 11:27 **MOT #4 MOT** test number 949821271210 Result ✓ Passed 2011-01-15 08:40 **MOT** #3 **MOT** test number 135465111045 Result ✓ Passed MOT #2 2010-01-30 11:49 **MOT** test number 101150130022 Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT test number

Result

Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	UN CONTRACTOR
Current registration	OK OK
Plate since	******
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-01-24
Last registration	2021-11-05
Complete history	See info



Registration #1	2007-01-24	22 mi
Registration #2	2010-01-30	34.212 mi
Registration #3	2010-01-30	34.216 mi
Registration #4	2011-01-15	43.509 mi
Registration #5	2011-09-28	51.184 mi
Registration #6	2012-09-26	58.180 mi
Registration #7	2013-09-30	66.128 mi
Registration #8	2014-09-22	76.174 mi
Registration #9	2016-01-19	92.766 mi
Registration #10	mm-m-m	11.777 46
	2003-29-29 2003-29-29	11.777 es
Registration #10	2000-20-20 2000-20-20 2000-20-20	11.777 es 11.777 es 11.777 es
Registration #10 Registration #11	100-10-10 100-10-10 100-10-10	11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12	100-10-10 100-10-10 100-10-10	11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12 Registration #13	100-10-10 100-10-10 100-10-10 100-10-10	11 177 46 11 177 46 11 177 46 11 177 46 11 177 46
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	100-10-10 100-10-10 100-10-10 100-10-10 100-10-10	11 177 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1793 kg
Max. allowed weight	2505 kg

### Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/: