



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 S
Colour	Black
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-09-07
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-09-05
<b>MOT pass rate</b>	81 %
<b>MOT passed</b>	13
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	21
<b>Total items failed</b>	4

**MOT #16** 2023-09-01 10:00**MOT test number** 915142631655**Result** ✓ Passed**Next expiry date** 2024-09-05

- Advice** Coil spring corroded all four (5.3.1 (b) (i))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive both front inner arches (5.3.6 (a) (i))
- Advice** Offside Oil leak, but not excessive driveshaft seal (8.4.1 (a) (i))

**MOT #15** 2022-09-06 09:59**MOT test number** 187852890561**Result** ✓ Passed

- Advice** Both rear coil springs corroded

**MOT #14** 2021-09-04 11:15**MOT test number** 131933814096**Result** ✓ Passed

**MOT #13** 2021-08-26 13:51**MOT test number** 883707295821**Result** ✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2020-11-30 15:03**MOT test number** 395446545021**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2019-05-30 10:39**MOT test number** 661184311403**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2018-05-18 10:05**MOT test number** 668205996599**Result** ✓ Passed

**MOT #9** 2017-05-31 10:50**MOT test number** 281988896955**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases flexy (7.1.2)**MOT #8** 2015-09-29 10:59**MOT test number** 685686006838**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-10-01 10:29**MOT test number** 358644074434**Result** ✓ Passed**MOT #6** 2013-10-04 09:30**MOT test number** 696697873292**Result** ✓ Passed**MOT #5** 2013-10-02 12:17**MOT test number** 227235573266**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #4** 2012-10-25 14:42**MOT test number** 166919592288**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #3** 2012-10-24 09:55**MOT test number** 946618892261**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2011-11-07 14:32**MOT test number** 418851811409**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-11-05 14:03**MOT test number** 691139300394**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	5 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-30
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2007-11-30	10 mi
Registration #2	2010-11-05	13.101 mi
Registration #3	2011-11-07	16.944 mi
Registration #4	2012-10-24	20.540 mi
Registration #5	2012-10-25	20.540 mi
Registration #6	2013-10-02	24.838 mi
Registration #7	2013-10-04	24.838 mi
Registration #8	2014-10-01	29.658 mi
Registration #9	2015-09-29	35.132 mi
Registration #10	2016-09-29	35.132 mi
Registration #11	2017-09-29	35.132 mi
Registration #12	2018-09-29	35.132 mi
Registration #13	2019-09-29	35.132 mi
Registration #14	2020-09-29	35.132 mi
Registration #15	2021-09-29	35.132 mi
Registration #16	2022-09-29	35.132 mi
Registration #17	2023-09-01	35.132 mi
Registration #18	2023-09-01	35.132 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	102315