



report date: 2024-03-29

General information

Make	MINI
Model	PACEMAN JOHN COOPER WORKS
Colour	Black
Year of manufacture	2014
Top speed	139 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	175 g/km
CO2 label	H



Internet history

Entry 1

Date	2021-08-25
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-11
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #9	2024-03-11 14:15
MOT test number	721609568183
Result	✓ Passed
Next expiry date	2025-03-11

MOT #8	2024-03-11 14:15
MOT test number	761224914611
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7	2023-03-09 10:58
MOT test number	726607414753
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2022-02-24 12:43**MOT test number** 361674678895**Result** ✓ Passed**Advice** Engine oil low**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**MOT #5** 2021-03-11 10:23**MOT test number** 837664573164**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake wear indicator lamp illuminated**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Both inner & outer tyre side walls damaged (5.2.3 (d) (ii))**MOT #4** 2020-03-06 12:06**MOT test number** 973662873977**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2019-03-06 09:25**MOT test number** 258152627301**Result** ✓ Passed**MOT #2** 2018-03-12 12:22**MOT test number** 836656630449**Result** ✓ Passed



MOT #1	2017-04-27 14:56
MOT test number	463244425853
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 March 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	11 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-29
Last registration	2024-03-11
Complete history	See info



Registration #1	2014-04-29	18 mi
Registration #2	2017-04-27	14.099 mi
Registration #3	2018-03-12	18.006 mi
Registration #4	2019-03-06	19.135 mi
Registration #5	2020-03-06	21.442 mi
Registration #6	2021-03-11	21.835 mi
Registration #7	2022-03-11	21.835 mi
Registration #8	2023-03-11	21.835 mi
Registration #9	2024-03-11	21.835 mi
Registration #10	2024-03-11	21.835 mi
Registration #11	2024-03-11	21.835 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1549 mm
Length	4133 mm
Wheel base	2595 mm
Kerb weight	1430 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A619J830