






report date: 2024-03-28

## General information

Make	FORD
Model	TRANSIT CONNECT T200 LR P/V
Colour	Silver
Year of manufacture	2012
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	74 BHP
Max. torque	220 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

## Entry 2

Date 2022-02-13

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## MOT history

MOT expiry date	2025-01-16
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	10

MOT #13	2024-01-10 09:36
MOT test number	348452827025
Result	✓ Passed
Next expiry date	2025-01-16
Advice Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))	
Advice Suspension component mounting prescribed area is corroded but not component (a) (i))	onsidered excessive (5.3.6

MOT #12	2	2023-01-16 14:36
MOT test	number	129817540119
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))	
Advice Brake pipe corroded, covered in grease or other material main brake pipes (1.1.11 (c))		
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #11	2022-01-17 10:27
MOT test number	259709070496
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #10** 2022-01-11 15:40 232427424749 **MOT** test number Result × Failed Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) Rear Direction indicator incorrect colour (4.4.3 (a)) Fail **Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

 MOT #9
 2020-12-07 17:18

 MOT test number
 926419811229

 Result
 ✓ Passed

 MOT #8
 2020-11-30 17:45

 MOT test number
 332622125583

 Result
 X Failed

Fail Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Central Exhaust has a major leak of exhaust gases Silencer Holed and Corroded (6.1.2 (a))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #7 2019-11-21 14:48

MOT test number 932979270035

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened nearside & offside (1.1.14 (a)

(ii))

Advice Brake pipe corroded, covered in grease or other material all coated (1.1.11 (c))

MOT #6 2019-11-20 10:11

**MOT test number** 207272968292

Result × Failed

**Advice** Brake pipe corroded, covered in grease or other material all coated (1.1.11 (c))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened nearside & offside (1.1.14 (a)

(ii))

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Fail Emissions not tested (8.2.2.2 (e))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nearside & offside (1.1.14 (a)

(ii))

**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT #5** 2018-11-07 09:42 **MOT** test number 498439567249 Result ✓ Passed **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c)) **Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Oil leak, but not excessive (8.4.1 (a) (i)) Advice Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #4** 2018-11-07 09:42 579603280413 **MOT** test number Result × Failed Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3		2017-11-13 09:11
MOT test	number	981168781009
Result		✓ Passed
Advice Nearside Front Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)		
<b>Advice</b> Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)		

CarCheck.co.uk page 6/14



Result

SP12WHT

report date: 2024-03-28

✓ Passed

MOT #2

MOT test number

Result

MOT #1

MOT test number

2016-11-30 15:06

955904265975

Passed

✓ Passed

MOT #1

699302195055

CarCheck.co.uk page 7/14



report date: 2024-03-28

### Tax & MOT check



Days left 279

MOT expiry date 16 January 2025

Full MOT history See MOT history

CarCheck.co.uk page 8/14



report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner	biotom,
UWNEI	nisioiv

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		<b>?</b>
THE PARTY OF THE P		
***************************************		
	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	NK SIE	
Plate since		
Current registration	NK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-31
Last registration	2024-01-10
Complete history	See info



Registration #1	2012-03-31	17 mi
Registration #2	2015-04-02	47.303 mi
Registration #3	2016-11-30	49.560 mi
Registration #4	2017-11-13	55.879 mi
Registration #5	2018-11-07	61.433 mi
Registration #6	2018-11-07	61.433 mi
Registration #7	2019-11-20	66.708 mi
Registration #8	2019-11-21	66.714 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Additional information

-	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BU98796

CarCheck.co.uk page 14/14